

Pre-exit - 15⁰⁰ } DR 0303

U2 F.A. B - CSR 52

U2 FA - C B Team Surge room

U2 FI I ⇒ Cable Loft - (PASS) Inert Gas Stop
Sheet Room

- 2 Findings in detail -

→ Findings → Minor

Gerry Wisera

Oil Filled Transformer not accounted for in FTH

380 gallons → Silicon

↳ A 37, B 34, Q 47

- Ignition sources ?

→ 2 opportunities to identify

- Maintenance & Surveillance

Screens more than minor.

They will ask for a duration.

SDP Help available

Manual actions ⇒ Outside MCR PA^{SC}_{SE}

H/38

License identified - Finding:
More than minor - Unresolved ⇒ Pending SDP analysis

They ⇒ Timeline performed. Validated. We did review some (not a of actions.)

Good job on Timeline verifying manual actions. Could be done. These could be done. Stone Mod returned.

Positive feedback on inspection
 - Good look
 - Fair
 - consistent in Region
 Didn't long with us continue doing this?
 Had been to Sunny/Hanna.
 Open after was a handle
 What dialog on SDP

Observation cold SD repair ???
 Licensing basis → No cold SD repair.

Phil Burns

9:00 a.m. exit.