

Pre-exit - 15⁰⁰ } DR 0303

02 F.A. B - CSR 52

02 FA - C B Team Surge Room

02 FI I ⇒ Cable Loft - (PASS) Inert Gas Stop
Sheet Room

- 2 Findings in detail -

→ Findings → Minor

Gerry Wisera

Oil Filled Transformer not accounted for in FTH

380 gallons → Silicon

→ A 37, B 34, Q 47

- Ignition sources ?

→ 2 opportunities to identify

- Maintenance & Surveillance

Screens more than minor.

They will ask for a duration.

SDP Help available

Manual actions ⇒ Outside MCR PA^{SC}_{SE}

H/38

License identified

- Finding: Pending SDP analysis.

More than minor.

Unresolved ⇒

They ⇒ Timeline performed. Validated. We did review some (not a of actions.)

Good job on Timeline verifying manual actions. Could be done. These could be done. Strong Mod returned.

Positive feedback on inspection
- Good look
- Fair
- Consistent in Region
Didn't long with the contract during the?
Had been to Sunny/Hanna.
Opn then was a handle
What dialog on SDP.

Observation cold SD repair ???
licensing basis → No cold SD repair.

Phil Burns

9:00 a.m. exit.