

**72.212 EVALUATION REPORT
PENDING CHANGE LOG**

No. Yr/Seq	Affected Sections	Description	Status *
01-01	3.1.3 and 3.2.3	Holtec ECO 1024-21 R.1, Dresden Calculations DRE00-0055 R.1 and DRE00-0022 R.2. ISFSI radiation dose.	RFI
02-01	1.3.7	Cask Transfer Facility Description	RFI
02-02	1.1.2, 1.1.3, 1.1.4, 1.1.8, 1.2.2.1.1, 1.2.2.2.1, 1.2.3.1, 1.3.2, 1.3.3, 1.4, 2.3.1, 3.2.1, 3.5, 3.6 and 5.0. Tables 1.1 and 1.2	Deleted procedures related to processing HI-STAR Casks.	RFI
02-03	1.3.3 and 1.4	Incorporates NRC issued ASME Code exceptions.	RFI
02-04	0.0, 1.0, 1.1.6, 1.3.4, 1.4, 2.4, 3.6 and 4.9	Incorporates NRC issued CoC 1008 Amendment No. 2	RFI
02-05	1.3.3 and 1.4	Incorporates NRC issued ASME Code exceptions (CTF).	RFI
03-01	2.1.1, 2.4 & 3.1.1	Addition of a third ISFSI pad per EC 8050	HFI
03-02	1.1.2	Change load testing of the HI-TRAC Trunnions to NDE testing in accordance with ANSI N14.6.	RFI
03-03	Sections 0.0, 1.0, 1.1, 1.1.1, 1.1.5, 1.1.6, 1.1.8, 1.1.9, 1.1.10, 1.2.2.2.2, 1.2.3, 1.2.3.1, 1.2.3.2, 1.2.3.2.2, 1.2.3.3, 1.2.3.5, 1.2.3.6, 1.3.2, 1.3.4.3, 1.3.4.6, 1.3.4.9, 1.3.5, 1.3.8, 1.4, 2.0, 2.1.2, 2.4, 3.0, 3.6, 4.2, 4.3, & 4.9 Table 1.2	Incorporates NRC issued HI-STORM 100 CoC 1014 Amendment No. 1 & FSAR Revision 1	PRAR
03-04	Table 1.1 & 1.2	Delete reference to DFP 0800-77 which is superseded by DFP 0800-71	RFI
03-05	Section 1.3.3 & 1.4	Incorporates NRC issued ASME Code Alternative (MPC 68-036 & 037 Closure Rings).	RFI
03-06	Table 1.2	Document exception for lifting HI-STORM Lid in vertical position.	PRAR

3-5-02
5-9-02

* RFI – Ready for Incorporation in next update
HFI – Hold for Incorporation for actions to be complete
PP – Pending Preparation

RII