



**TXU Energy**  
**Comanche Peak Steam**  
**Electric Station**  
P.O. Box 1002 (E01)  
Glen Rose, TX 76043  
Tel: 254 897 5209  
Fax: 254 897 6652  
mike.blevins@txu.com

**Mike Blevins**  
Senior Vice President & Principal Nuclear Officer

Ref: 10CFR50.55a

CPSES-200302398  
Log # TXX-03189  
File # 10010.1  
RP-39

November 6, 2003

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES) -UNIT 2  
DOCKET NO. 50-446  
UNIT 2, SEVENTH REFUELING OUTAGE (2RF07)  
STEAM GENERATOR INSERVICE INSPECTION TUBE PLUGGING  
SPECIAL REPORT NO. 2-SR-03-001-00

Gentlemen:

Attached is a 15-day special report submitted pursuant to CPSES Technical Specification 5.6.10a. If there are any questions or if additional information is needed, please contact Mr. Bob Kidwell at (254) 897-5310.

This communication contains no new licensing basis commitments regarding CPSES Units 1 and 2.

AD47

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

TXX-03189

Page 2 of 2


Sincerely,

TXU Generation Company LP

By: TXU Generation Management Company LLC,  
Its General Partner

M. R. Blevins

Senior Vice President and Principal Nuclear Officer

By:   
Roger D. Walker  
Regulatory Affairs Manager

RJK/rjk

Attachment

cc - B. Mallett, Region IV  
W. D. Johnson, Region IV  
M. C. Thadani, NRR  
Resident Inspectors, CPSES

Attachment to TXX-03189

Page 1 of 1

**TXU ENERGY  
COMANCHE PEAK STEAM ELECTRIC STATION - UNIT 2  
SPECIAL REPORT NO. 2-SR-03-001-00  
UNIT 2, SEVENTH REFUELING OUTAGE (2RF07)  
STEAM GENERATOR INSERVICE INSPECTION TUBE PLUGGING**

This letter provides the Inservice Inspection (ISI) Special Report on the steam generator tube ISI for Comanche Peak Steam Electric Station's seventh refueling outage (2RF07) on Unit 2. This report is being provided to you pursuant to CPSES Technical Specification 5.6.10a.

Steam Generators 1 and 4 were inspected during 2RF07. The examinations were completed on October 24, 2003. The number of tubes plugged during this outage in each steam generator is as follows:

CPSES Unit 2 Steam Generator No. 1: Three (3)

CPSES Unit 2 Steam Generator No. 4: One (1)

Additional details on the plugged tubes and inspection effort will be provided in the 12-month report pursuant to CPSES Technical Specification 5.6.10b.