

DEATH VALLEY  
JUNCTIONS



EXPLANATION

- OS11 PNEZOMETER (OS INDICATES WELL DRILLED FOR THIS STUDY)
- OS10 PNEZOMETER WELLS
- Q FLOWING WELL
- SPRING OR SEEP
- OVERTRANSPIRATION PNEZOMETER SITE
- TENSIONMETER SITE
- AREA COVERED BY SALT CRUST

1:12000 Map of the Franklin Lake area showing the location of wells and springs



III  
APERTURE  
CARD

8410110371

DOI

8410110371  
9/18/84