

6/27/

WM Record File
101.2

WM Project 10
Docket No. ✓
PDR ✓
LPDR ✓

Distribution:
Wright
(Return to WM, 623-SS) no



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555

6/27/83

To: Joe LaRue, Rockwell
From: Wright

Attached are
comments on some
of the figures in
SER Chapt. 3.

Note: This material was
given by hand to LaRue on
6/27/83.

8307220157 830627
PDR WASTE
WM-10 PDR

00553

SCR Chapter 3 Maps / X-sections

FIGURE	COMMENT
3-13 (3.5-10) Generalized Geologic Map	Too Generalized - some faults not shown (eg. Rattlesnake Fault) Need a proper geologic map
3-16 (3.5-13) General x-section through RRL	schematic, no boring control shown, RRL not shown
3-18 (3.5-16) Location Map	Incomplete, location of x-sections not shown, not all borings penetrating the candidate horizons are shown.
3-22 (3.5-21) Fence diagram	Not located on Fig 3-18
3-23 (3.5-22) - Fence diagram	North arrow not oriented properly, not located on figure 3-18
3-44 (3.6-28) Gamma-Gamma log response	Wrong figure referenced for location, figure inconsistent with text.
3 3-47 (3.7-5) Generalized Tectonic Map	Inadequate
3-48 (3.7-9) Faults of the Paso Basin	Not all faults shown, location of San Jolla Fault inconsistent with text.

3-51 (3.7-29)

Top of Basalt Contour Map

Not all data points used to construct the contours are shown, area contoured centered on Cold Creek Syncline, not RRL and "controlled area".

3-52 (3.7-29)

Interpretive bedrock structure map

Known and inferred structures are not differentiated.