

KMHaas
GCWithrow
MJBielinski

KEPallagi
WJTrubilowicz
MEVanAlst
SRCook

NPAD - BRP
WGSnell - NRC
LEDarrah

EMEvans
RCSarki
JO'Hearn - BNFL

Weekly Condition Report Log

20-Nov-03

DOCUMENT	TITLE/DESCRIPTION	SIGNIFICANCE	REPORTABLE	ORIG. DEPT.	ORIG. DATE	EVALUATOR
C-BRP-03-0262	DROPPED PLYWOOD SHEET - SAFETY A 4' x 8' plywood sheet went over the East Reactor Deck handrail, sliding along the Reactor Containment Sphere wall until it came to rest upon a electrical cable tray mounting bracket below the 616' elevation grating. No personal injury or equipment damage occurred from this event.	4	No	DM	11/12/2003	
C-BRP-03-0263	SLURRY WALL INCIDENT - SAFETY Employee following safety rope boundary in route to the tool room came to what appeared to be a corridor between roped off area. Employee turned towards the tool room and fell into the slurry filled trench. Trench area appeared to be solid ground but was actually two day old slurry, which quickly gave way buring the employee to the waist. Employee suffered minor strain to the left calf muscle. No first aid rendered or requested.	4	No	RP	11/12/2003	

A-4