



CONDITION REPORT

CR-ANO-1-2001-0726

Originator: Hendrix,Ronald D

Originator Phone: 5854

Originator Group: Eng P&C Fire Protection Staff

Supervisor Name: Rispoli,Ronald D

Discovered Date: 06/22/2001 07:44

Initiated Date: 06/22/2001 07:49

Condition Description:

The NRC Fire Protection Triennial Inspection team has identified a potential Appendix R, 3G2 non compliance concern in Fire Zone 99-M. This concern is related to lack of one hour fire barriers on red train raceways traversing the zone. Prefire plans currently identify all manual actions required to be initiated should the circuits in the unprotected conduits suffer fire damage. The affected components remain operable with the establishment of a roving fire watch.

Immediate Action Description:

Recommend that a roving fire watch post be established to ensure operability of the effected components.

Suggested Action Description:

Review Pre Fire plans for this area to identify opportunities to enhance guidance to operations.

CR 1-2001-0723 identifies a similar condition in Fire Zone 98-J. Fire Protection Engineering recommends closure of this CR to 1-2001-0723.

99M

roving fire watch

To: Rebecca Neese

From: Russ

268

1/2