

Department of Energy

Richland Operations Office
P.O. Box 550
Richland, Washington 99352

86-QSB-154

.07

JAN 12 P12:00

DEC 3 1 1986

General Manager Rockwell Hanford Operations Richland, Washington

Dear Sir:

RESPONSE TO CORRECTIVE ACTION OF AUDIT FINDING 85-10-RHO-1 BWIP SITE DEPARTMENT, GEOSCIENCE AND GEOTECHNICAL LIBRARY, OCTOBER 1-4, 1985

Your additional corrective action as stated in Rockwell letter 31038.Rl, dated September 26, 1986, "Corrective Action Response to Audit Finding 85-10-RHO-1," is acceptable. As stated in my letter 86-QSB-29, dated June 25, 1986, we will verify corrective actions after the affected activities have resumed from the current stop work.

Should you need any assistance in closing these findings, please contact Mr. W. B. Williams on 6-4206.

Sincerely,

R. P. Saget, Director Quality Systems Division

MAC:WBW QA02K6.Q4

Attachment

cc w/attach:

D. C. Gibbs, Rockwell

J. P. Knight, DOE/HQ

D. C. Newton, DOE/HQ

J. J. Linehan, NRC

L. B. Ibe, Weston

T. Husseman, Washington State Department of Ecology

D. Stewart-Smith, Oregon State Department of Energy

B. Burke, Confederated Tribes of the Umatilla Indian Reservation

R. Halfmoon, Nez Perce Indian Tribe

R. Jim, Yakima Indian Nation

8702240269	B61231	
PDR WASTE WM-10	PDR	:

WM Record File	WM Project
Distribution:	PHildenbrand

(Return to WM, 623-SS)

2269



Department of Energy

Richland Operations Office P.O. Box 550 Richland, Washington 99352

86-QSB -29

JUN 25 1986

General Manager Rockwell Hanford Operations Richland, Washington

Dear Sir:

VERIFICATION OF CORRECTIVE ACTION RESPONSES TO AUDIT 85-10-RHO, BWIP SITE DEPARTMENT, GEOSCIENCES AND GEOTECHNICAL LIBRARY, OCTOBER 1-4, 1985.

An attempt was made to verify corrective actions stated in your letter 28938. RI with the following results:

Audit Finding	Results
85-10-RHO-01	Still Open - no attempt to verify, see below .
85-10-RHO-02	Still Open - revision to BOP C-3.12 not issued
85-10-RHO-03	Still Open - revision to BOP C-3.10 not issued
85-10-RHO-04	<u>Still Open</u> - same as 85-10-RHO-03 above
85-10-RHO-05	Still Open - same as 85-10-RHO-02 above
85-10-RHO-06	<u>Closed</u> - changed to an observation per DOE letter 86-BOS-10.

Since revisions to procedures are also a condition for restarting work stopped by Stop Work Order BSW0-86-004, the status of corrective action on findings 85-10-RHO-02 through 85-10-RHO-05 will be a consideration in the process for lifting the Stop Work Order. Finding 85-10-RHO-01 remains open as the corrective action committed to was an improvement in Rockwell's training program. Training in revision to procedures is the last action needed to close out the other audit findings and, therefore, 85-10-RHO-01 will not be considered for closure until last.

As soon as a date has been identified for lifting that portion of the stop work order affecting these audit findings, you should send me a new response for corrective action. Your new response should include the date corrective action will now be completed and the name of the individual to contact for everification.

Should you need any assistance in closing these findings, please contact Mr. Wesley Williams (6-9945).

Sincerely,

Underside SIGNED BY R. P. SAGET

R. P. Saget, Chief Quality Systems Branch Basalt Waste Isolation Branch

BWI:WW 32F6.Q1

cc: D. C. Gibbs, Rockwell
E. Sulek, Weston
J. P. Knight/D. C. Newton, DOE-HQ
Audit File

bcc: R. P. Saget, BWI
T. H. Davies, BWI
P. E. Rasmussen, AMO
W. B. Williams, MAC
BWI Record Copy
BWI Rdg. File
AMC Rdg. File
HACRES AMC
MAC Rdg. File

ffice	BWI:MAC	MAG	AMQ /	BWI		*	
6-7334	(previous concurrence 6/18/86) Silkerkood	Rasmútsen	sager			
URHAME P	6/19/96	4218	1,12/1	(12)			:
DATE Þ	0/10/00	· · · · · · · · · · · · · · · · · · ·			• • • • • • • • • • • • • • • • • • • •	******]

Rockwell Hantord Operations P.O. Box 800 Richland, WA 99352 Rockwell International

September 26, 1986

In reply, refer to letter 31038.R1

Iir. O. L. Olson, Director Basalt Waste Isolation Division Department of Energy Richland Operations Office Richland, Nashington 99352

Dear Hr. Olson:

CORRECTIVE ACTION RESPONSE TO AUDIT FINDING 85-10-RHO-1 (Contract DE-ACO6-77RL01030)

References: (a) Letter, October 22, 1985, O. L. Olson to P. G. Lorenzini, same subject

- (b) Letter, December 22, 1985, L. R. Fitch toO. L. Olson, same subject
- (c) Letter, June 25, 1986, R. P. Saget to General Hanager, Rockwell Hanford Operations, same subject

On October 22, 1985, the subject audit finding was transmitted to Rockwell Hanford Operations (Rockwell) [Reference (a)]. Rockwell responded to the audit finding on December 20, 1985 [Reference (b)]. On June 25, 1986, the Department of Energy-Richland Operations Office (DOE-RL) indicated that resolution of the audit finding was dependent upon the activities planned during the recovery from the general stop work order [Reference (c)]. To comply with this direction, Rockwell is recommending that the due date for implementation of the corrective action be changed to the date that the partial lifting of the suspension occurs. Additionally, the corrective action should be revised as follows:

a) All text relevant to the Integrating Contractor role in the Project Qualification and Training Program will be included in the Project Management Plan and an annex to the Management and Integration Plan.

RECEIVED

SEP3 0 1986

DOF-PL/BY/I DCC



Mr. O. L. Olson Page 2 September 26, 1986

- b) All Project Hanagement Procedures relevant to the Integrating Contractor role in the Project Qualification and Training Program will be completed.
- c) The Integrating Contractor Qualification and Training staff will be trained and qualified.

Your concurrence with these proposed revisions is requested. If you have any questions, please contact W. G. Keltner at 376-5167:

Very truly yours,

D. C. Gibbs, Director

Basalt Waste Isolation Project

DCG/cda

cc: J. H. Anttonen - DOE-RL

K. W.; Bracken - DOE-RL

P. E. Rasmussen - DOE-RL