



FirstEnergy Nuclear Operating Company

5501 North State Route 2  
Oak Harbor, Ohio 43449

Mark B. Bezilla  
Vice President - Nuclear

419-321-7676  
Fax: 419-321-7582

Docket Number 50-346  
License Number NPF-3  
Serial Number 3032

March 5, 2004

United States Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555-0001

Subject: Davis-Besse Nuclear Power Station Emergency Plan and Emergency Implementing Procedures

Ladies and Gentlemen:

During an evaluation of the Emergency Preparedness program by the Davis-Besse Nuclear Quality Assessment staff, in accordance with 10CFR50.54(t), an oversight was discovered in transmission of the Davis-Besse Nuclear Power Station (DBNPS) Emergency Plan and Emergency Implementing Procedures per 10 CFR 50.4. Although the Emergency Plan and Emergency Implementing Procedures have been transmitted to the NRC Region III Office and Headquarters through our Document Control staff, the plan and procedures have not been recently transmitted in accordance with the DBNPS regulatory process to ensure compliance with 10 CFR 50.4. The enclosed Emergency Implementing Procedures and Emergency Plan were current as of February 18, 2004.


This condition was entered in the DBNPS Corrective Action Program to be evaluated and corrected. To rectify this condition please find enclosed current copies of the DBNPS Emergency Plan (Revision 22) and the Emergency Implementing Procedures, Volumes A, B, and C (the Emergency Implementing Procedures also contain the DBNPS Off-Normal Procedures and are included in this submittal). Although distribution of the Emergency Plan and Emergency Implementing Procedures to the NRC was not administratively in accordance with 10 CFR 50.4, the process of changing the plan has been completed in accordance with 10 CFR 50.54 (q). The DBNPS process requires review of the changes to ensure no decrease in effectiveness of the plan. FENOC understands the regulation allows the licensee to make changes to the Emergency Plan without NRC approval only if the changes do not decrease the effectiveness of the plan. The DBNPS Emergency Plan, as changed, continues to meet the requirements of 10 CFR 50.47 (b) and 10 CFR 50, Appendix E.

A045

Docket Number 50-346  
License Number NPF-3  
Serial Number 3032  
Page 2 of 2

If you have any questions, please contact Mr. Greg A. Dunn, Manager – Regulatory Affairs, at (419) 321-8450.

Very truly yours,

A handwritten signature in black ink, appearing to read "Mr. B. Bejlich". The signature is fluid and cursive, with the first name "Mr." written in a smaller, more formal script than the last name "Bejlich".

Enclosures

cc: Regional Administrator, NRC Region III  
DB-1 NRC/NRR Senior Project Manager, w/o  
DB-1 Senior Resident Inspector  
Utility Radiological Safety Board, w/o

Docket Number 50-346  
License Number NPF-3  
Serial Number 3032  
Enclosure 1  
Page 1 of 1

### COMMITMENT LIST

The following list identifies those actions committed to by the FirstEnergy Nuclear Operating Company (FENOC), Davis-Besse Nuclear Power Station in this document. Any other actions discussed in the submittal represent intended or planned actions by FENOC. They are described only as information and are not regulatory commitments. Please notify the Manager – Regulatory Affairs (419-321-8450) at Davis-Besse of any questions regarding this document or associated regulatory commitments.

#### COMMITMENTS

#### DUE DATE

None

N/A

Docket Number 50-346  
License NPF-3  
Serial Number 3032  
Enclosure 2  
Page 1 of 2

**LIST OF DOCUMENTS INCLUDED IN SUBMITTAL**

**NOTE**

The enclosed Emergency Plan and Emergency Implementing Procedures were current as of February 18, 2004.

	Revision #	Effective Date
Davis-Besse Emergency Plan	22	3/28/01
Davis-Besse Evacuation Time Estimate	5	2/26/03

**EMERGENCY IMPEMENTING PROCEDURES:**

Procedure #	Procedure Title	Revision #	Effective Date
RA-EP-01500	Emergency Classification	03	07/10/03
RA-EP-01600	Unusual Event	01	08/01/03
RA-EP-01700	Alert	01	08/01/03
RA-EP-01800	Site Area Emergency	01	08/01/03
RA-EP-01900	General Emergency	02	08/01/03
RA-EP-02010	Emergency Management	04	08/01/03
RA-EP-02110	Emergency Notification	05	06/17/03
RA-EP-02220	Emergency Control Center Activation And Response	02	01/09/03
RA-EP-02230	Dose Assessment Center Activation And Response	00	05/29/02
RA-EP-02240	Offsite Dose Assessment	01	02/02/04
RA-EP-02245	Protective Action Guidelines	01	01/10/03
RA-EP-02250	Radiation Monitoring Team Surveys	03	09/02/03
RA-EP-02260	Radiological Controls In The DBAB	02	12/17/03
RA-EP-02270	Facilities Support	02	12/02/03
RA-EP-02310	Technical Support Center Activation And Response	02	01/09/03
RA-EP-02320	Emergency Technical Assessment	01	04/04/00
RA-EP-02410	Operations Support Center Activation And Response	05	08/13/03
RA-EP-02420	Search And Rescue	01	03/29/99
RA-EP-02510	Emergency Security Organization Activation And Response	05	08/13/03

Docket Number 50-346  
License NPF-3  
Serial Number 3032  
Enclosure 2  
Page 2 of 2

Procedure #	Procedure Title	Revision #	Effective Date
RA-EP-02520	Assembly And Accountability	03	8/12/02
RA-EP-02530	Evacuation	00	02/11/99
RA-EP-02550	Offsite Personnel and Vehicle Monitoring and Decontamination	00	12/12/02
RA-EP-02610	Emergency Radiation Protection Organization Activation and Response	04	02/25/03
RA-EP-02620	Emergency Dose Control And Potassium Iodide Distribution	03	08/01/03
RA-EP-02640	Station Radiological Surveys and Controls During Emergencies	02	08/01/03
RA-EP-02710	Reentry	02	11/25/03
RA-EP-02720	Recovery Organization	05	07/19/03
RA-EP-02000	Medical Emergencies	01	1/31/02
RA-EP-02800	Preparation And Transport Of Contaminated Injured Personnel	02	01/21/04
RA-EP-02807	Emergency Helicopter Landing Zones	02	01/09/03
RA-EP-02810	Tornado	03	05/30/03
RA-EP-02820	Earthquake	05	11/13/03
RA-EP-02830	Flooding	01	02/25/03
RA-EP-02840	Explosion	01	03/05/03
RA-EP-02850	Hazardous Chemical And Oil Spills	04	01/23/03
RA-EP-02861	Radiological Incidents	03	06/30/03
RA-EP-02864	Containment Evacuation	00	04/29/02
RA-EP-02870	Station Isolation	02	11/13/02
RA-EP-02880	Internal Flooding	02	11/05/02