March 18, 2004

MEMORANDUM TO: Stephen Dembek, Chief, Section 2

Project Directorate IV

Division of Licensing Project Management

FROM: Bo M. Pham, Project Manager, Section 2 /RA/

Project Directorate IV

Division of Licensing Project Management

SUBJECT: SAN ONOFRE NUCLEAR GENERATING STATION – CONFERENCE

CALL SUMMARY REGARDING REGENERATIVE HEAT EXCHANGER

WELD FAILURE

On February 9, 2004, the staff held a conference call with Southern California Edison (SCE) regarding PNO-IV-04-003, "Southern California Edison, Unit 3 Shutdown to Repair a Letdown System Piping Leak." A summary of the event is available in ADAMS under accession number ML040270293. The list of participants in the conference call is attached.

During the call, SCE presented the initial root cause findings and their determination of the failure mechanism to the staff. SCE attributed the cracked weld at San Onofre Nuclear Generating Station, Unit 3 to excessive vibration from adjacent piping and pump operating combinations. The staff asked additional questions pertaining to the licensee's examinations and methodology. The staff also requested to review the licensee's nondestructive examination data and final metallurgical evaluation reports. The licensee agreed to supply these upon the completion of their evaluation.

Docket No. 50-362

Attachment: Conference Call Participants

CONFERENCE CALL PARTICIPANTS

February 9, 2004

SOUTHERN CALIFORNIA EDISON COMPANY

Ed Scherer
Jack Rainsberry
Geoff Cook
Kevin Flynn
Riyad Qashu
Mehrdad Hojati
Mike Short
Al Meichler

NRC

Stephanie Coffin
Don Naujock
Thomas McLellan
Jai Rajan
Bo Pham
Wayne Sifre, Region IV
Ramon Azua, Region IV
Clyde Osterholtz, Region IV
Mark Sitek, Region IV

March 18, 2004

MEMORANDUM TO: Stephen Dembek, Chief, Section 2

Project Directorate IV

Division of Licensing Project Management

FROM: Bo M. Pham, Project Manager, Section 2

Project Directorate IV

Division of Licensing Project Management

SUBJECT: SAN ONOFRE NUCLEAR GENERATING STATION – CONFERENCE

CALL SUMMARY REGARDING REGENERATIVE HEAT EXCHANGER

/RA/

WELD FAILURE

On February 9, 2004, the staff held a conference call with Southern California Edison (SCE) regarding PNO-IV-04-003, "Southern California Edison, Unit 3 Shutdown to Repair a Letdown System Piping Leak." A summary of the event is available in ADAMS under accession number ML040270293. The list of participants in the conference call is attached.

During the call, SCE presented the initial root cause findings and their determination of the failure mechanism to the staff. SCE attributed the cracked weld at San Onofre Nuclear Generating Station, Unit 3 to excessive vibration from adjacent piping and pump operating combinations. The staff asked additional questions pertaining to the licensee's examinations and methodology. The staff also requested to review the licensee's nondestructive examination data and final metallurgical evaluation reports. The licensee agreed to supply these upon the completion of their evaluation.

Docket No. 50-362

Attachment: Conference Call Participants

DISTRIBUTION:

PUBLIC COsterholtz, Region IV WSifre, Region IV PDIV-2 r/f MSitek, Region IV RAzua, Region IV

RidsNrrDlpmLpdiv (H. Berkow) DNaujock SCoffin RidsNrrPMBPham TMcLellan TChan

RidsNrrLAEPeyton JRajan

ACCESSION NO: ML040780574 NRR-001

OFFICE	PDIV-2/PM	PDIV-2/LA	PDIV-2/SC
NAME	BPham:esp	EPeyton	SDembek
DATE	3/17/04	3/16/04	3/17/04

OFFICIAL RECORD COPY

DOCUMENT NAME: C:\ORPCheckout\FileNET\ML040780574.wpd