

UNIT SHUTDOWNS AND POWER REDUCTIONS
FOR OCTOBER 1988

Docket No.: 50-309
Unit: Maine Yankee
Date: 29/Nov/88
Completed By: J. M. TAYLOR
Telephone: 207-882-6321
Page: 1 of 1

Number	30-88-10		
Date	881014		
Type (1)	S		
Duration (Hours)	410.3		
Reason (2)	C		
Method (3)	1		
LER #	N/A		
System Code (4)	ZZ		
Component Code (5)	ZZZZZZ		
Cause and Corrective Action	Shutdown to begin refueling outage.		

1. TYPE:
(F)orced
(S)cheduled

2. REASON
A-Equipment Failure
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training &
License Examination

2. REASON: (cont)
F-Administrative
G-Operational Error
H-Other (Explain)

3. METHOD:
1-Manual
2-Manual Scram
3-Automatic Scram
4-Other (Explain)

4. SYSTEM CODE:
Exhibit G-Instructions
for Preparation of Data
Entry Sheets for
Licensee Event Report
(LER) File (NUREG.0161)

5. COMPONENT CODE:
Exhibit I-Same source
as above.

8812290237 881209
PDR ADOCK 05000029
R PDC