



DEC 24 1959

allowed by 10 CFR Part 20, Standards for Protection Against Radiation, for unrestricted areas. The activity discharged probably arose from decontamination and laundry activities and is thought by Mr. Beam to be mostly cobalt 60 and iridium 192. No detectable alpha activity has been observed.

- 4. On November 25, 1959 we wrote you a memorandum and attachments concerning the Curtiss-Wright Corporation, Research Division, Quehanna, Pennsylvania, License No. 37-2416-2, 10 CFR 30 - Suspected Spillage of Iridium-192 During Transit. The investigation concerning this suspected spillage indicated no evidence of contamination.

In view of the above information, which we believe supports the view that it is extremely unlikely that there has been carelessness in handling fissionable material or that excessive radioactive materials have been dumped into Mosquito Creek, we do not plan to contact Mr. T. McKinney, President, Mosquito Creek Sportsmen's Association, Frenchville, Pennsylvania, at this time.

*Johnson*  
12/23

OFFICE ▶	INS	INS				
SURNAME ▶	PAMORRIS <i>PAM</i>	CANLISON <i>C</i>				
DATE ▶	12/23/59	12-24				