

Sequoyah Nuclear Plant
PER Workorder Needing MRC or Supervisor Review Printout

Page 11
PER256s
01/29/02

WorkOrder/Sta	Entry Dt	Department	Identified By	Supervisor	Systems Units	Recommend Levl	Oper A	Repo S	Pot	Pot	Pot
						Recommend Org	FE		ME	Oper	Repo

the card replacement heard the adapter fall and took the necessary steps to locate the missing part. Due to its location, planning to remove additional cards was obtained.

***** IMMEDIATE ACTION TAKEN *****

02-000822-000 01/28/2002 OPS

I 17:11

N

***** DESCRIPTION OF CONDITION *****

The current Appendix - R program requires the Reactor Vessel Head Vent Valve fuses to be removed as a pre-emptive manual action for any declared Appendix-R fire. For fires in the 6.9 kv Shutdown Board Rooms, the accomplishment of this action may require the use of fire fighter 'turn-out' gear. Operations shift personnel are no longer qualified to utilize 'turn-out' gear nor does Operations maintain 'turn-out' gear for Operations shift personnel.

***** IMMEDIATE ACTION TAKEN *****

AW
BDB-S