



May 6, 2004

U. S. Nuclear Regulatory Commission  
Washington, DC 20555

**ATTENTION:** Document Control Desk

**SUBJECT:** Calvert Cliffs Nuclear Power Plant  
Unit No. 1; Docket No. 50-317  
Report of Steam Generator Tube Plugging

---

**REFERENCE:** (a) Calvert Cliffs Unit 1 Technical Specification 5.6.9.a

As required by Reference (a), this letter reports the number of tubes plugged or repaired in the Calvert Cliffs Unit 1 steam generators during the recently completed Inservice Inspection:

- In the No. 11 Steam Generator, no tubes were plugged and no tubes were repaired this outage. Prior to this outage, no tubes had been plugged and no tubes had been repaired in the No. 11 Steam Generator. To date, a total of 0 tubes are plugged and 0 tubes are repaired in the No. 11 Steam Generator.
- In the No. 12 Steam Generator, no tubes were plugged and no tubes were repaired this outage. Prior to this outage, no tubes had been plugged and no tubes had been repaired in the No. 12 Steam Generator. To date, a total of 0 tubes are plugged and 0 tubes are repaired in the No. 12 Steam Generator.

Should you have questions regarding this matter, we will be pleased to discuss them with you.

Very truly yours,

A handwritten signature in black ink, appearing to read "KJN", written over a horizontal line.

KJN/CAN/bjd

cc: J. Petro, Esquire  
J. E. Silberg, Esquire  
Director, Project Directorate I-1, NRC  
G. S. Vissing, NRC

H. J. Miller, NRC  
Resident Inspector, NRC  
R. I. McLean, DNR

A001