

Serial: RNP-RA/04-0053

MAY 1 8 2004

United States Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261/LICENSE NO. DPR-23

STEAM GENERATOR TUBE PLUGGING REPORT FOR REFUELING OUTAGE 22

Ladies and Gentlemen:

In accordance with the H. B. Robinson Steam Electric Plant, Unit No. 2, Technical Specifications 5.6.8, "Steam Generator Tube Inspection Report," Paragraph a, Progress Energy Carolinas, Inc., also known as Carolina Power and Light Company, submits the attached steam generator tube plugging report for Refueling Outage 22. The steam generator tube plugging was completed on May 7, 2004.

If you have any questions concerning this matter, please contact me.

Sincerely,

C. T. Baucom

R.a. Crandall for

Supervisor - Licensing/Regulatory Programs

JMG/jmg

Attachment

c: NRC Resident Inspector, HBRSEP L. A. Reyes, NRC, Region II

C. P. Patel, NRC, NRR

A047

United States Nuclear Regulatory Commission Attachment to Serial: RNP-RA/04-0053 Page 1 of 1

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

STEAM GENERATOR TUBE PLUGGING REPORT FOR REFUELING OUTAGE 22

Steam Generator	Number of Tubes Plugged During RO 22
Α	0
В	5
С	2