

From notes to SRI while on leave:

Monday, 4/19

2. 50.72 Sunday night due to shutdown cooling isolation actuation on high pressure. Shutdown cooling was not in service at the time, they were warming it up and took a little too long getting letdown through RWCU reestablished.

From DER tracking list:

DER#	Unit	Description	Cause	NRC?	Comments
2037	2	Unexpected pressure rise while securing from warmup of SDC	Ops		50.72

B-12