

September 23, 2004

Mr. David A. Christian  
Senior Vice President - Chief Nuclear Officer  
Virginia Electric and Power Company  
Innsbrook Technical Center  
5000 Dominion Blvd.  
Glen Allen, Virginia 23060-6711

SUBJECT: NORTH ANNA POWER STATION, UNIT 2 - RESPONSE TO NRC  
BULLETIN 2003-02, "LEAKAGE FROM REACTOR PRESSURE VESSEL  
LOWER HEAD PENETRATIONS AND REACTOR COOLANT PRESSURE  
BOUNDARY INTEGRITY" (TAC NO. MC0549)

Dear Mr. Christian:

On August 21, 2003, the U.S. Nuclear Regulatory Commission (NRC) issued NRC Bulletin 2003-02, "Leakage from Reactor Pressure Vessel Lower Head Penetrations and Reactor Coolant Pressure Boundary Integrity," to the industry. This Bulletin informed addressees that current methods of inspecting the reactor pressure vessel (RPV) lower heads may need to be supplemented with bare-metal visual inspections in order to detect reactor coolant pressure boundary leakage and requested these addressees provide the NRC with information related to inspections that have been performed to verify the integrity of the RPV lower head penetrations.

The Bulletin requested that addressees provide a description of the RPV lower head penetration inspection program that would be implemented at their respective plants during the next and subsequent refueling outages. This description was to include the extent of the inspection, the inspection methods to be used, the qualification standards for the inspection methods, the process used to resolve the source of findings of boric acid deposits or corrosion, the inspection documentation to be generated, and the basis for concluding that their plant satisfied applicable regulatory requirements related to the structural and leakage integrity of the RPV lower head penetrations.

By letter dated November 17, 2003, Virginia Electric and Power Company (VEPCO) provided its response to this request. VEPCO indicated it planned to perform a bare-metal visual examination of all 50 RPV lower head penetrations during the Spring 2004 refueling outage at North Anna Power Station, Unit 2. In its same response, VEPCO committed to performing a 360-degree bare-metal visual examination of these 50 penetrations during each subsequent refueling outage at North Anna, Unit 2, although VEPCO indicated that this inspection schedule may be revised in the future. As such, VEPCO is requested to notify the NRC staff in writing of any changes to this commitment prior to implementation.

The Bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection and the methods used, a description of the as-found condition of the lower head, any findings of

relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated June 24, 2004, VEPCO provided a summary of its inspection results at North Anna, Unit 2. VEPCO reported it had performed a 360-degree bare-metal visual examination of the 50 RPV lower head penetrations with no evidence of penetration leakage or RPV lower head wastage observed.

The NRC staff has completed its review of VEPCO's responses to NRC Bulletin 2003-02. Accordingly, TAC No. MC0549 is closed for North Anna, Unit 2

Sincerely,

*/RA/*

Stephen Monarque, Project Manager, Section 1  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-339

cc: See next page

relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated January 30, 2004, VEPCO provided a summary of its inspection results at North Anna, Unit 2. VEPCO reported it had performed a 360-degree bare-metal visual examination of the 50 RPV lower head penetrations with no evidence of penetration leakage or RPV lower head wastage observed.

The NRC staff has completed its review of VEPCO's responses to NRC Bulletin 2003-02. Accordingly, TAC No. MC0549 is closed for North Anna, Unit 2.

Sincerely,

*/RA/*

Stephen Monarque, Project Manager, Section 1  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-339

cc: See next page

Distribution:

PUBLIC	SMonarque (paper copy)	RGramm
PDII-1 Rdg.	EDunnington (paper copy)	MJRoss-Lee
GCherukenki	PDII-1/RF	EHackett
JNakoski	LMarsh	OGC
ESullivan		

ADAMS ACCESSION NUMBER: ML042680295

OFFICE	PDII-1/PM	PDII-2/LA	EMCB	PDII-1/SC
NAME	SMonarque	EDunnington	ESullivan	MJRoss-Lee
DATE	9/16/04	9/21/04	09/16/2004	9/22/04

**OFFICIAL RECORD COPY**

North Anna Power Station, Units 1 & 2

cc:

Mr. C. Lee Lintecum  
County Administrator  
Louisa County  
Post Office Box 160  
Louisa, Virginia 23093

Mr. Jack M. Davis  
Site Vice President  
North Anna Power Station  
Post Office Box 402  
Mineral, Virginia 23117-0402

Ms. Lillian M. Cuoco, Esq.  
Senior Counsel  
Dominion Resources Services, Inc.  
Building 475, 5th floor  
Rt. 156, Rope Ferry Road  
Waterford, Connecticut 06385

Mr. Richard H. Blount, II  
Site Vice President  
Surry Power Station  
Virginia Electric and Power Company  
5570 Hog Island Road  
Surry, Virginia 23883-0315

Dr. W. T. Lough  
Virginia State Corporation Commission  
Division of Energy Regulation  
Post Office Box 1197  
Richmond, Virginia 23218

Dr. Robert B. Stroube, MD, MPH  
State Health Commissioner  
Office of the Commissioner  
Virginia Department of Health  
Post Office Box 2448  
Richmond, Virginia 23218

Old Dominion Electric Cooperative  
4201 Dominion Blvd.  
Glen Allen, Virginia 23060

Mr. William R. Matthews  
Vice President-Nuclear Operations  
Virginia Electric and Power Company  
Innsbrook Technical Center  
5000 Dominion Boulevard  
Glen Allen, Virginia 23060-6711

Mr. Chris L. Funderburk, Director  
Nuclear Licensing & Operations Support  
Dominion Resources Services, Inc.  
Innsbrook Technical Center  
5000 Dominion Blvd.  
Glen Allen, Virginia 23060-6711

Office of the Attorney General  
Commonwealth of Virginia  
900 East Main Street  
Richmond, Virginia 23219

Senior Resident Inspector  
North Anna Power Station  
U. S. Nuclear Regulatory Commission  
1024 Haley Drive  
Mineral, Virginia 23117