1650 Calvert Cliffs Parkway Lusby, Maryland 20657 410.495.4101 410.495.4787 Fax



October 14, 2004

U. S. Nuclear Regulatory Commission Washington, DC 20555

ATTENTION:

Document Control Desk

SUBJECT:

Calvert Cliffs Nuclear Power Plant

Unit Nos. 1 & 2; Docket Nos. 50-317 & 50-318

September 2004 Operating Data Reports

The subject reports are being sent to you as required by Technical Specification 5.6.4.

Should you have questions regarding this matter, we will be pleased to discuss them with you.

Very truly yours,

KJN/CAN/bjd

Attachments

cc:

J. Petro, Esquire

J. E. Silberg, Esquire R. V. Guzman, NRC

S. J. Collins, NRC

Resident Inspector, NRC

R. I. McLean, DNR

S. Mainieri, INPO

K. N. Larson, ANI

Certified Mail 17000 1670 0001 9799 6093

1624

OPERATING DATA REPORT

*** ******** ****** ******** ******

Docket No. 50-317 Calvert Cliffs Unit 1 October 1, 2004 Prepared by Herman O. Olsen

Telephone: (410) 495-6734

REPORTING PERIOD

DESIGN ELECTRICAL RATING (NET MWe)

MAXIMUM DEPENDABLE CAP'Y (NET MWe)

SEPTEMBER 2004 845 870

	This month	Year- to-Date	Cumulative	
	This month	to-bate	to Date	
1. NUMBER OF HOURS REACTOR WAS CRITICAL	720.0	5,865.9	197,915.3	
2. HOURS GENERATOR ON LINE	720.0	5,826.1	194,711.8	
3. UNIT RESERVE SHUTDOWN HOURS	0.0	0.0	0.0	
4. NET ELECTRICAL ENERGY GENERATED (MWH)	626,231	5,001,878	159,701,593	

UNIT SHUTDOWNS

DOCKET NO. UNIT NAME 50-317

DATE

Calvert Cliffs - U1
October 1, 2004

COMPLETED BY TELEPHONE

Herman O. Olsen (410) 495-6734

REPORTING MONTH September 2004

NO.	DATE	TYPE F: FORCED S: SCHEDULED	DURATION (HOURS)	REASON 1	METHOD OF SHUTTING DOWN ²	CAUSE/CORRECTIVE ACTIONS COMMENTS
						There were no shutdowns this month.
ļ		;	·]			
:						1
ł						
]			

- ¹ Reason:
- A Equipment Failure
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training & License Examination
- F Administrative
- G Operational Error
- H Other

- ² Method:
- 1 Manual
- 2 Manual Scram.
- 3 Automatic Scram.
- 4 Continued
- 5 Other

DOCKET NO. 50-317 CALVERT CLIFFS - UNIT 1 October 1, 2004

SUMMARY OF OPERATING EXPERIENCE

September 2004

The unit began the month at 100% power.

On 09/04/04 at 2200, power was reduced to 87% for Main Turbine Valve Testing. Testing was completed and power was returned to 100% on 09/05/04 at 0110.

On 09/10/04 at 2010 power was reduced to approximately 95% for waterbox cleaning. Power was restored to 100% on 09/12/04 at 0035 after completion of waterbox cleaning.

The unit operated at 100% power for the remainder of the month.

OPERATING DATA REPORT

Docket No. 50-318

Calvert Cliffs Unit 2

October 1, 2004

Prepared by Herman O. Olsen

Telephone: (410) 495-6734

REPORTING PERIOD

DESIGN ELECTRICAL RATING (NET MWe)

MAXIMUM DEPENDABLE CAP'Y (NET MWe)

SEPTEMBER 2004 845 858

	This month	Year- to-Date	Cumulative to Date
1. NUMBER OF HOURS REACTOR WAS CRITICAL	720.0	6,525.4	191.252.2
2. HOURS GENERATOR ON LINE	720.0	6,520.6	189,358.8
3. UNIT RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
4. NET ELECTRICAL ENERGY GENERATED (MWH)	604.825	5.624.743	156.368.033

UNIT SHUTDOWNS

DOCKET NO. 50-318
UNIT NAME Calvert
DATE October
COMPLETED BY Herman

Calvert Cliffs-U2 October 1, 2004

TELEPHONE

Herman O. Olsen (410) 495-6734

REPORT MONTH September 2004

NO.	DATE	TYPE F: FORCED S: SCHEDULED	DURATION (HOURS)	REASON ¹	METHOD OF SHUTTING DOWN ²	CAUSE/CORRECTIVE ACTIONS COMMENTS
						There were no shutdowns this month.

- 1 Reason:
- A Equipment Failure
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training & License Examination
- F Administrative
- G Operational Error
- H Other

- ² Method:
- 1 Manual
- 2 Manual Scram
- 3 Automatic Scram
- 4 Continued
- 5 Other

DOCKET NO. 50-318 CALVERT CLIFFS - UNIT 2 October 1, 2004

SUMMARY OF OPERATING EXPERIENCE

September 2004

The unit began the month at 100% power.

On 09/10/04 at 2240 power was reduced to 86% for Main Turbine Valve Testing. Testing was completed and power was restored to 100% on 09/11/04 at 0037.

On 09/18/04 at 1258 a rapid down power was required due to decreasing condenser vacuum. Power was stabilized at approximately 87% while trouble shooting took place. It was determined that a high differential pressure, due to sea grass intrusion, on the Amertap screens prevented moving the screens. Circulating Water Pump 25 was secured and the screens were repositioned. Power was increased to 98% and stabilized at 2338 due to condenser differential temperature.

On 09/19/04 at 0140 power was reduced to 86% for waterbox cleaning. Waterbox cleaning was completed and power was returned to 100% at 2217.

On 09/20/04 at 2030 power was reduced to 93% to clean 21A waterbox. Power was returned to 100% On 09/21/04 at 0400. At 2203 power was reduced to 95% to clean 21B waterbox. Waterbox cleaning was completed and power was returned to 100% on 09/22/04 at 0412. At 2207 power was reduced to 95% to clean 23A waterbox. Waterbox cleaning was completed and power was returned to 100% on 09/23/04 at 0555.

The unit operated at 100% power for the remainder of the month.