

3

3-MB-SYS

CM-LCM

WO #: 2719090
 LEAD WORK CENTER: EMS LEAD DISCP: PR&C
 COMPONENT: 3EMBNC01**CKTBRK
 COMP DESC: VOLTAGE REGULATOR CABINET
 LOCATION: ZJ3A

PRIORITY: 6
SEQUENCE: 3
DUE:

PROBLEM DESC:

Following the U3 trip of 6-14-2004, it was discovered through evaluation that the MEL/Fix Field circuits did not response correctly. Troubleshoot the casue of this problem,

WORK DESC:

.....END WORK DESC

TECH SPEC: N	WK QR: N	SAFETY REQD: N	MATLS REQD: -BLANK-
SEISMIC CAT: 3	SPECIAL CONCERNS: N		V CAT: N
RCS PERT:	SCFD REQD: N	INSL REQD: N	EQ MODE:
COATING:	CRDL #:		
PERMIT #:			
POSTED PERMITS			
REP REQD: N	REP #:		

OTHER LEADS (DISCP):
 OTHER SUPPORT (DISCP):

PREPARER	DATE	TECHNICAL APPROVAL	DATE
		NOT REQUIRED	
TEAM LEADER	DATE	RELEASING ORGANIZATION	DATE

PLANNER BACKEND REVIEW REQUIRED

C/35

(WORK ORDER CLOSING INFORMATION)

3

3-MB-SYS

CM-LCM

WO #: 2719090
LEAD WORK CENTER EMS LEAD DISCP: PR&C
COMPONENT: 3EMBNC01**CKTBRK
COMP DESC: VOLTAGE REGULATOR CABINET
LOCATION: ZJ3A

PRIORITY: 6
SEQUENCE: 3
DUE:

.....END WORK DESC

WORK STARTDATE/TIME: WORK COMPLETE DATE/TIME:

JOB SUMATION:

BADGE # EMPLOYEE NAME TOTAL ACTUAL HOURS

MATERIAL REQUESTS # 5

TEAM LEADER / DATE:

RETEST REFERENCE DOCUMENT: