

James R. Becker Vice President-Diablo Canyon Operations and Station Director Diablo Canyon Power Plant P.O. Box 56 Avila Beach, CA 93424

805.545.3462 Fax: 805.545.4234

October 15, 2004

PG&E Letter DCL-04-132

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Docket No. 50-275, OL-DPR-80 Docket No. 50-323, OL-DPR-82 Diablo Canyon Units 1 and 2 Monthly Operating Report for September 2004

Dear Commissioners and Staff:

Enclosed is the Monthly Operating Report for Diablo Canyon Power Plant, Units 1 and 2, for September 2004. This report is submitted in accordance with Technical Specification 5.6.4 and NRC Generic Letter 97-02.

Sincerely,

James R. Becker

Imp/3386/R0264600

Enclosures

cc/enc:

Paul R. Fox, American Nuclear Insurers

Robert D. Glynn, Jr.

Bruce S. Mallett, NRC Regional Administrator, Region IV

David L. Proulx, NRC Senior Resident Inspector

Gregory M. Rueger

Girija S. Shukla, NRC Project Manager

INPO Record Center

IE24

OPERATING DATA REPORT

DOCKET NO. UNIT NAME DATE COMPLETED BY TELEPHONE	50-275 Diablo Canyon 1 October 11, 2004 Larry Parker (805) 545-3386		- - - -	
REPORTING PERIO		1.103.00 1.087.00		
4. Number of Hou 5. Reserve Shutde	rs the Reactor was Critical rs Generator On-line own Hours nergy Generated (MWHrs)	This Month 720.00 720.00 0.00 793.103.00	Yr-to-Date 4.792.37 4.661.11 0.00 4.806.629.00	Cumulative 147.779.17 146.130.71 0.00 151.598.359.00

UNIT SHUTDOWNS

		Type			Method of	
No.	Date	F: Forced	Duration	Reason 1	Shutting	Cause & Corrective Action
	Date	S: Scheduled	(Hours)	Reason	Down 2	Comments

SUMMARY: Unit 1 remained in Mode 1 (Power Operation), at approximately 100 percent power during September 2004. On September 28, 2004, at 1015 PDT, a 6.0M earthquake in Parkfield. CA (approximately 50 miles from the plant) was felt in the control room, and triggered the plant earthquake force monitor at greater than 0.01g. In accordance with the Emergency Plan, Operators declared an Unusual Event (Reference NRC Event Number 41076). Both units remained at 100 percent power, and subsequent inspections found no damage due to the earthquake.

Reason:

- A Equipment Failure (Explain)
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training & License Examination
- F Administration
- G Operational Error (Explain)
- H Other (Explain)

Z

Method:

- 1 Manual
- 2 Manual Trip/Scram
- 3 Automatic Trip/Scram
- 4 Continuation
- 5 Other (Explain)

OPERATING DATA REPORT

DOCKET NO.	50-323	
UNIT NAME	Diablo Canyon 2	
DATE	October 11, 2004	
COMPLETED BY	Larry Parker	
TELEPHONE	(805) 545-3386	
REPORTING PERIO	September 2004	

1.	Design Electrical Rating	1,119.00
2.	Maximum Dependable Capacity (MWe-Net)	1,087.00

En 222

		<u>inis montri</u>	<u> Yr-to-Date</u>	<u>Cumulative</u>
3.	Number of Hours the Reactor was Critical	720.00	6.575.00	145.224.90
4.	Number of Hours Generator On-line	720.00	6.575.00	143,689.13
5.	Reserve Shutdown Hours	0.00	0.00	0.00
6.	Net Electrical Energy Generated (MWHrs)	759,718.00	7.051,304.00	151,468,521.00
				

TL:- 88--46

UNIT SHUTDOWNS

	l	Type			Method of	Ì
11-	D-1-	F: Forced	Duration	Reason 1	Shutting	Cause & Corrective Action
No.	Date	S: Scheduled	(Hours)	Reason	Down 2	Comments

SUMMARY: Unit 2 began September in Mode 1 (Power Operation), at approximately 100 percent power. On September 17, 2004. Operators performed a planned ramp of the unit to approximately 50 percent power in order to remove biofouling from the main condenser tube sheet and water box. On September 18, 2004, after completing condenser maintenance, Operators ramped the unit to approximately 100 percent power. On September 28, 2004, at 1015 PDT, a 6.0M earthquake in Parkfield. CA (approximately 50 miles from the plant) was felt in the control room, and triggered the plant earthquake force monitor at greater than 0.01g. In accordance with the Emergency Plan. Operators declared an Unusual Event (Reference NRC Event Number 41076). Both units remained at 100 percent power, and subsequent inspections found no damage due to the earthquake.

Reason:

1

- A Equipment Failure (Explain)
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training & License Examination
- F Administration
- G Operational Error (Explain)
- H Other (Explain)

Method:

- 1 Manual
- 2 Manual Trip/Scram
- 3 Automatic Trip/Scram
- 4 Continuation
- 5 Other (Explain)