



NOV 01 2004
LR-N04-0475

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

10CFR21 FINAL REPORT
Fisher Pneumatic Instrument Relays with Nitrile Elastomer Diaphragms
SALEM GENERATING STATION UNITS 1 AND 2
FACILITY OPERATING LICENSE NOS. DPR-70 AND DPR-75
DOCKET NOS. 50-272 AND 50-311

This letter transmits PSEG's final evaluation to the potential 10CFR21.21(b) received from Fisher Controls. Pursuant to the notification requirements of 10CFR21.21(b), PSEG Nuclear LLC (PSEG) provided an interim report, LR-N04-0377, dated August 20, 2004. The subject report, FIN 2004-02, "Fisher Pneumatic Instrument Relays with Nitrile Elastomer Diaphragms" was issued on June 23, 2004. PSEG has completed the evaluation of the report mentioned above and has determined that a substantial safety hazard does not exist and that the cited condition is not reportable under 10CFR21.21(b).

Should you have any questions regarding this submittal, please contact K. Myers at (856) 339-2328.

Sincerely,

A handwritten signature in black ink, appearing to read "Christina Perino".

Christina Perino
Director – Licensing & Nuclear Safety

IE19

C Mr. S. Collins, Administrator - Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. D. Collins
Licensing Project Manager - Salem
U. S. Nuclear Regulatory Commission
One White Flint North
Mail Stop 08B1A
11555 Rockville Pike
Rockville, MD 20852

USNRC Senior Resident Inspector - Salem (X24)

Mr. K. Tosch, Manager IV
Bureau of Nuclear Engineering
P. O. Box 415
Trenton, NJ 08625