SURVEILLANGE REGUINENTS (COntinued)		
SURVEILLANCE		FREQUENCY
SR 3.6.5.1.3	Verify bypass leakage is less than or equal to the bypass leakage limit.  However, during the first unit startup following bypass leakage testing performed in accordance with this SR, the acceptance criterion is ≤ 10% of the drywell bypass leakage limit.	SR 3.0.2 is not applicable for extensions > 12 months  24 months following 2 consecutive tests with bypass leakage greater than the bypass leakage limit until 2 consecutive tests are less than or equal to the bypass leakage limit  AND  48 months following a test with bypass leakage limit  AND  48 months following a test with bypass leakage greater than the bypass leakage limit  AND  120 months except that the next drywell leak rate test performed after the June 24, 1994 test shall be performed no later than June 23, 2009.