



ENGINEERING CONSULTING SERVICES, LTD.
Geotechnical • Construction Materials • Environmental

December 15, 2004

Mr. John D. Kinneman
U.S. Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

RE: Amendment to NRC License No. 37-30921-01

03036600

Dear Mr. Kinneman:

This is a request for amendment to Material License No. 37-30921-01.
My intention is to procure a Troxler Nuclear Density Gauge model # 3440 in the near future. Below you will find a detailed description of the desired addition to our license.

Materials to be Possesed and Proposed Uses

RADIOISOTOPE	MANUFACTURER MODEL No.	QUANTITY	MOST COMMON USE	OTHER USES
Cesium 137	Sealed source Troxler/model 3440	No single source to exceed 10mCi	Measure physical properties of materials	None
Americium 241/Be	Sealed source Troxler/model 3440	No single source to exceed 50mCi	Measure physical properties of materials	None

If you should have any questions or need further information, please feel free to give us a call.

Respectfully Submitted,

ENGINEERING CONSULTING SERVICES, LTD.

Rohan O. Perch, Sr.
Radiation Safety Officer

136138

NMSS/RGNI MATERIALS-002

52 Grumbacher Road, Suite A-5 • York, Pennsylvania 17402 • (717) 767-4788 • FAX (717) 767-5658

Aberdeen, MD • Atlanta, GA • Austin, TX • Baltimore, MD • Chantilly, VA • Charlotte, NC • Chicago, IL • Cornelia, GA • Dallas, TX • Danville, VA • Frederick, MD • Fredericksburg, VA • Greensboro, NC
Greenville, SC • Norfolk, VA • Orlando, FL • Research Triangle Park, NC • Richmond, VA • Roanoke, VA • San Antonio, TX • Williamsburg, VA • Wilmington, NC • Winchester, VA • York, PA

*Testing Services Only

This is to acknowledge the receipt of your letter/application dated

12/05/2004, and to inform you that the initial processing which includes an administrative review has been performed.

AMEND. 37-30921-01 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 136138.

When calling to inquire about this action, please refer to this control number. You may call us on (610) 337-5398, or 337-5260.

BETWEEN: : (FOR LFMS USE)
 : INFORMATION FROM LTS
 : -----
 :
 License Fee Management Branch, ARM : Program Code: 03121
 and : Status Code: 0
 Regional Licensing Sections : Fee Category: 3P
 : Exp. Date: 20140630
 : Fee Comments: _____
 : Decom Fin Assur Reqd: N
 : ::

LICENSE FEE TRANSMITTAL

A. REGION I

1. APPLICATION ATTACHED
 Applicant/Licensee: ENGINEERING CONSULTING SERVICES, LTD
 Received Date: 20041215
 Docket No: 3036600
 Control No.: 136138
 License No.: 37-30921-01
 Action Type: Amendment

2. FEE ATTACHED
 Amount: _____
 Check No.: _____

3. COMMENTS
 Signed M.A. Berkine
 Date 12/15/2004

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered /__/)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for:
 Amendment _____
 Renewal _____
 License _____

3. OTHER _____

Signed _____
 Date _____