



DEC 13 2004

SERIAL: HNP-04-169

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

SHEARON HARRIS NUCLEAR POWER PLANT
DOCKET NO. 50-400/LICENSE NO. NPF-63
MONTHLY OPERATING REPORT

Ladies and Gentlemen:

In accordance with Technical Specification 6.9.1.5 for the Harris Nuclear Plant, Carolina Power & Light Company, doing business as Progress Energy Carolinas, Inc., is providing the enclosed report of operating statistics and shutdown experience for the month of November 2004.

Sincerely,

A handwritten signature in black ink, appearing to read 'David H. Corlett', written in a cursive style.

David H. Corlett
Supervisor, Licensing/Regulatory Programs
Harris Nuclear Plant

DHC/mgw

Enclosure

c: Mr. R. A. Musser (NRC Senior Resident Inspector, HNP)
Mr. C. P. Patel (NRC Project Manager, HNP)
Dr. W. D. Travers (NRC Regional Administrator, Region II)

Progress Energy Carolinas, Inc.
Harris Nuclear Plant
P.O. Box 165
New Hill, NC 27562

JE24

OPERATING DATA REPORT

DOCKET NO. 050-400
UNIT NAME Shearon Harris Nuclear Power Plant
DATE December 7, 2004
COMPLETED BY Michael S. Matheny
TELEPHONE (919) 362-2335

REPORTING PERIOD November 2004
 (Month/Year)

	MONTH	YEAR TO DATE	CUMULATIVE
1. Design Electrical Rating: (MWe-Net)	941.7	N/A	N/A
2. Maximum Dependable Capacity: (MWe-Net)	900.0	N/A	N/A
3. Number of Hours the Reactor Was Critical:	372.3	7,002.7	133,146.8
4. Number of Hours the Generator Was On Line:	323.5	6,945.0	131,976.5
5. Unit Reserve Shutdown Hours:	0.0	0.0	0.0
6. Net Electrical Energy (MWH):	268,635.0	6,314,878.0	112,114,315.0

**APPENDIX B
UNIT SHUTDOWNS**

DOCKET NO. 050-400
UNIT NAME Shearon Harris Nuclear Power Plant
DATE December 7, 2004
COMPLETED BY Michael S. Matheny
TELEPHONE (919) 362-2335

REPORTING PERIOD

November 2004
(Month/Year)

NO.	DATE (yymmdd)	TYPE F: FORCED S: SCHEDULED	DURATION (HOURS)	REASON (1)	METHOD OF SHUTTING DOWN (2)	CAUSE/CORRECTIVE ACTIONS COMMENTS
04-002	041015	S	396.5	C	4	Scheduled shutdown for RFO-12.

SUMMARY: The unit was shutdown for refueling on 10/15/04. The outage was extended by approximately one week due to unplanned repairs on the Main Feedwater Isolation Valves. The unit was returned to service on 11/17/2004.

(1) Reason:

- A - Equipment Failure (Explain)
- B - Maintenance or Test
- C - Refueling
- D - Regulatory Restriction
- E - Operator Training/License Examination
- F - Administrative
- G - Operational Error (Explain)
- H - Other (Explain)

(2) Method:

- 1 - Manual
- 2 - Manual Trip/Scram
- 3 - Automatic Trip/Scram
- 4 - Continuation
- 5 - Other (Explain)