

RECEIVED  
REGION 1



**CARPENTER**  
Specialty Alloys

'05 JAN 11 P12:36

Carpenter Technology Corporation  
P.O. Box 14662  
Reading, PA 19612-4662

Tel: 610.208.2000

January 7, 2005

U.S. Nuclear Regulatory Commission  
Region 1  
475 Allendale Road  
King of Prussia, PA 19406-1415

Attention: Material Licensing

Re: Renewal of License #37-08210-01  
Docket #030-06185

Dear Sir:

I am requesting an amendment to our license #37-08210-01.

We have discontinued the use of our Kevex 6700 XRF analyzer with a model 0202 sealed source. The sealed source was return to John Harrison (License #1655-31) in Auburn, California in July 2004 as directed by the manufacturer. In it's place we have acquired a portable Niton model Xli/XLp, XRF analyzer containing cadmium and americium and it's use will be as listed on the SSD certificate #MA-1159-D-101-B of 6/25/04.

Please amend section #7 of our license by replacing the Kevex information with the Niton information.

Should there be any additional questions, please contact Joan Fessler at 610-208-2457.

Sincerely yours,

Joan I. Fessler  
Health & Safety Engineer

136271

NMSS/RGNI MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

1/7/2005, and to inform you that the initial processing which includes an administrative review has been performed.

☒ AMEND. 37-08210-01  
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 136271.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.

BETWEEN: : (FOR LFMS USE)  
: INFORMATION FROM LTS  
: -----  
:   
License Fee Management Branch, ARM : Program Code: 03120  
and : Status Code: 0  
Regional Licensing Sections : Fee Category: 3P  
: Exp. Date: 20110228  
: Fee Comments: \_\_\_\_\_  
: Decom Fin Assur Req'd: N  
: ::

LICENSE FEE TRANSMITTAL

A. REGION I

1. APPLICATION ATTACHED

Applicant/Licensee: CARPENTER TECHNOLOGY CORPORATION  
Received Date: 20050111  
Docket No: 3006185  
Control No.: 136271  
License No.: 37-08210-01  
Action Type: Amendment

2. FEE ATTACHED

Amount: \_\_\_\_\_  
Check No.: /

3. COMMENTS

Signed M. A. Perkins  
Date 1/12/05

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered /\_\_/)

1. Fee Category and Amount: \_\_\_\_\_

2. Correct Fee Paid. Application may be processed for:

Amendment \_\_\_\_\_  
Renewal \_\_\_\_\_  
License \_\_\_\_\_

3. OTHER \_\_\_\_\_  
\_\_\_\_\_

Signed \_\_\_\_\_  
Date \_\_\_\_\_