

ISSUES FROM TP TFI 2004-007

CR's

1. Unapproved local manual operator actions but they were found to be feasible. (Met 71111.05 ENCC. 2 criteria)

04-0385

2. TD FP auto start ckt

04-0477

3. Sizing of oil retention walls.

04-0610

4. MOV-4-626 FZ 67

also thermal shock concern?

04-0688

5. MOV-3/4-716A FZ 106

04-0683

6. Spurious closure of LCV-3/4-115B FZ 63, 67

7. Access to vital areas room during fire

8. Sec. guard support during ONOP-105

04-0686

9. Fire detection spacing in FZ 67

04-0476

10. Lack of area-wide detection in FZ 97 & suppression.

03-1330

04-0698

11. 20 min vs 13 min

12. ONOP vs EOP

H-5