

March 7, 2005

Mr. Ronald A. Jones  
Vice President, Oconee Site  
Duke Energy Corporation  
7800 Rochester Highway  
Seneca, SC 29672

SUBJECT: OCONEE NUCLEAR STATION, UNIT 3 - RESPONSE TO NUCLEAR REGULATORY COMMISSION BULLETIN 2003-02, "LEAKAGE FROM REACTOR PRESSURE VESSEL LOWER HEAD PENETRATIONS AND REACTOR COOLANT PRESSURE BOUNDARY INTEGRITY"  
(TAC NO. MC0552)

Dear Mr. Jones:

On August 21, 2003, the Nuclear Regulatory Commission (NRC) issued NRC Bulletin 2003-02, "Leakage from Reactor Pressure Vessel Lower Head Penetrations and Reactor Coolant Pressure Boundary Integrity," to the industry. This bulletin informed addressees that current methods of inspecting the reactor pressure vessel (RPV) lower heads may need to be supplemented with bare-metal visual inspections in order to detect reactor coolant pressure boundary leakage. The bulletin also requested these addressees to provide the NRC with information related to inspections that have been performed to verify the integrity of the RPV lower head penetrations.

The bulletin requested that addressees provide a description of the RPV lower head penetration inspection program that would be implemented at their respective plants during the next and subsequent refueling outages. This description was to include the extent of the inspection, the inspection methods to be used, the qualification standards for the inspection methods, the process used to resolve the source of findings of boric acid deposits or corrosion, the inspection documentation to be generated, and the basis for concluding that their plant satisfied applicable regulatory requirements related to the structural and leakage integrity of the RPV lower head penetrations.

By letter dated September 18, 2003, Duke Energy Corporation (Duke) provided its response to this request for Oconee Nuclear Station (Oconee), Unit 3. Duke indicated it planned to perform a bare-metal visual examination of the RPV lower head, including a 360-degree examination of all RPV lower head penetrations during the Fall 2004 refueling outage at Oconee, Unit 3. Additionally, Duke stated that the information obtained from these inspection findings and industry developments on the RPV lower head penetrations will be used to determine the type of examinations that will be performed during future refueling outages, beyond the Fall 2004 refueling outage at Oconee. The NRC staff notes that there are a number of ongoing industry and NRC staff activities related to developing criteria for RPV lower head penetrations inspections. As such, the NRC staff expects that the criteria for these inspections will involve periodic bare-metal visual examinations or their equivalent.

Ronald A. Jones

- 2 -

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated January 14, 2005, Duke provided a summary of its inspection results at Oconee, Unit 3. Duke reported it had performed a bare-metal visual inspection of the RPV lower head, including 360-degree examinations around 100 percent of the RPV lower head penetrations. Duke did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Duke's responses to NRC Bulletin 2003-02, the NRC staff finds that Duke has met the reporting requirements of the bulletin for Oconee. Accordingly, TAC No. MC0552 is closed for Oconee, Unit 3.

Sincerely,

*/RA/*

Leonard N. Olshan, Sr. Project Manager, Section 1  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. 50-287

cc: See next page

Ronald A. Jones

- 2 -

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated January 14, 2005, Duke provided a summary of its inspection results at Oconee, Unit 3. Duke reported it had performed a bare-metal visual inspection of the RPV lower head, including 360-degree examinations around 100 percent of the RPV lower head penetrations. Duke did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Duke's responses to NRC Bulletin 2003-02, the NRC staff finds that Duke has met the reporting requirements of the bulletin for Oconee. Accordingly, TAC No. MC0552 is closed for Oconee, Unit 3.

Sincerely,

*/RA/*

Leonard N. Olshan, Sr. Project Manager, Section 1  
Project Directorate II  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket Nos. 50-287

cc: See next page

Distribution:

PUBLIC	SMonarque	RGramm	
PDII-1 RF	LOlshan	JNakoski	CHawes (Hard Copy)
GCheruvenci	ESullivan	LMarsh	OGC

ADAMS ACCESSION NUMBER: ML050630264

NRR-106

OFFICE	PDII-1/PM	PDII-1/LA	LPM	EMCB	PDII-1/SC
NAME	LOlshan	CHawes	SMonarque	ESullivan	JNakoksi
DATE	03/ 07 /2005	03/ 07 /2005	03/ 07 /2005	3/3/05	03/ 07 /2005

**OFFICIAL RECORD COPY**

Oconee Nuclear Station, Units 1, 2, and 3

cc:

Ms. Lisa F. Vaughn  
Duke Energy Corporation  
Mail Code - PB05E  
422 S. Church St.  
P.O. Box 1244  
Charlotte, NC 28201-1244

Ms. Anne W. Cottingham, Esq.  
Winston and Strawn  
1400 L St, NW  
Washington, DC 20005

Manager, LIS  
NUS Corporation  
2650 McCormick Dr., 3rd Floor  
Clearwater, FL 34619-1035

Senior Resident Inspector  
U.S. Nuclear Regulatory Commission  
7812B Rochester Highway  
Seneca, SC 29672

Mr. Henry Porter, Director  
Division of Radioactive Waste Management  
Bureau of Land and Waste Management  
Dept. of Health and Env. Control  
2600 Bull St.  
Columbia, SC 29201-1708

Mr. Michael A. Schoppman  
Framatome ANP  
1911 North Ft. Myer Dr.  
Suite 705  
Rosslyn, VA 22209

Mr. B. G. Davenport  
Regulatory Compliance Manager  
Oconee Nuclear Site  
Duke Energy Corporation  
ON03RC  
7800 Rochester Highway  
Seneca, SC 29672

Ms. Karen E. Long  
Assistant Attorney General  
NC Department of Justice  
P.O. Box 629  
Raleigh, NC 27602

Mr. R. L. Gill, Jr.  
Manager - Nuclear Regulatory  
Issues and Industry Affairs  
Duke Energy Corporation  
526 S. Church St.  
Mail Stop EC05P  
Charlotte, NC 28202

Mr. Richard M. Fry, Director  
Division of Radiation Protection  
NC Dept of Environment, Health, & Natural  
Resources  
3825 Barrett Dr.  
Raleigh, NC 27609-7721

Mr. Peter R. Harden, IV  
VP-Customer Relations and Sales  
Westinghouse Electric Company  
6000 Fairview Road  
12th Floor  
Charlotte, NC 28210

Mr. Henry Barron  
Group Vice President, Nuclear Generation  
and Chief Nuclear Officer  
P.O. Box 1006-EC07H  
Charlotte, NC 28201-1006