From:

"Mike Griffin" <mgriffin@citcnet.net>

To:

"Lusher, John" <jhl@nrc.gov>, "Miesbach, Dave" <david.miesbach@ndeq.state.ne.us>,

"Dave Carlson" < Dave. Carlson@ndeq.state.ne.us>

Date:

3/1/05 12:03PM

Subject:

Late verification sample - Crow Butte, Doc. 40-8943

Guys:

Attached is a letter to Mike Linder describing the late verification sample collection on CM5-19 last week. Hard copy is in the mail. John, I copied you on this since it was reported to the State but it will also be documented in our self-identified violations file for NRC.

Mike

Mail Envelope Properties (4224A04A.897:7:10391)

Subject:

Late verification sample

Creation Date:

3/1/05 12:02PM

From:

"Mike Griffin" <mgriffin@citcnet.net>

Created By:

mgriffin@citcnet.net

Recipients

nrc.gov

twf4_po.TWFN_DO JHL (John Lusher)

ndeq.state.ne.us

Dave.Carlson (Dave Carlson) david.miesbach (Dave Miesbach)

Post Office

twf4_po.TWFN_DO

Route

nrc.gov

ndeq.state.ne.us

Files

Size

Date & Time

289

03/01/05 12:02PM

TEXT.htm

MESSAGE

654

late Excursion sampling.doc

239616

Mime.822

330729

Options

Expiration Date:

None

Priority:

Standard

Reply Requested:

No

Return Notification:

None

Concealed Subject:

No

Security:

Standard

CROW BUTTE RESOURCES, INC.

86 Crow Butte Road P.O. Box 169 Crawford, Nebraska 69339-0169



(308) 665-2215 (308) 665-2341 – FAX

March 1, 2005

Mr. Michael Linder, Director Nebraska Department of Environmental Quality PO Box 98922 Lincoln, Nebraska 68509-8922

Subject:

Failure to Meet Excursion Monitoring Schedule Requirement Class III Underground Injection Control Permit NE0122611

Dear Mr. Linder:

The referenced Class III Underground Injection Control (UIC) permit requires that Crow Butte Resources, Inc. (CBR) collect verification samples for monitor wells that exceed the Upper Control Limit (UCL)¹. The purpose of these verification samples is to determine that accurate monitoring results have been obtained and that a valid excursion condition exists. A verification sample must be obtained within 24 hours of the time that the analytical results from the first sample are available. If this second sample is below the UCLs, a third verification sample must be obtained within 48 hours of the time that the first sample was taken.

Monitor well CM5-19 is a perimeter monitor well in Mine Unit 5. The routine biweekly sample for CM5-19 was obtained at 0705 hours on February 22, 2005. The results from that sample were available by mid-morning on February 22 and exceeded the UCLs. A verification sample was obtained at 1138 hours on February 22. This sample was below the UCLs. By permit requirement, a third verification sample should have been obtained by 0705 hours on February 24. Contrary to this requirement, CBR obtained the third verification sample at 1254 hours on February 25, approximately 30 hours after the required time.

This failure was attributed to an oversight by the environmental sampling staff to obtain the third sample as scheduled due to inadequate directions from supervision. A contributing factor is differing requirements for obtaining the third sample under CBR's source materials license issued by the US Nuclear Regulatory Commission (i.e., 48 hours after the second sample is obtained). The corrective action to prevent a reoccurrence of this failure is increased attention by supervision in instances where verification samples are required.

¹ Class III Underground Injection Control Permit NE0122611, Part II, Section B, Table 2.3 footnote.

CROW BUTTE RESOURCES, INC.



Mr. Mike Linder March 1, 2005 Page 2

CBR believes that the potential impact of this monitoring oversight was minimal. The second sample had indicated that the well was not on excursion and that the first sample was not representative of the water quality conditions in CM5-19. The third sample confirmed this conclusion, albeit 30 hours later than required. Had the second sample been in error, the potential existed that an excursion would have been verified 30 hours late. However, CBR has been overproducing in the mine unit areas adjacent to CM5-19 due to trends in the data and this action would most likely not have been changed.

If you have any questions, please do not hesitate to call me at (308) 665-2215.

Sincerely, CROW BUTTE RESOURCES, INC.

Michael L. Griffin Manager of Health, Safety, and Environmental Affairs

cc: U.S. Nuclear Regulatory Commission
Mr. John Lusher - ADDRESSEE ONLY
Fuel Cycle Licensing Branch
Mail Stop T-8A33
Washington, DC 20555

Nebraska Department of Environmental Quality Mr. Dave Carlson, Program Specialist Northwest Field Office 250 Main Street Chadron, Nebraska 69337

Mr. Steve Collings Crow Butte Resources, Inc. 274 Union Boulevard Suite 310 Lakewood, Colorado 80228

CROW BUTTE RESOURCES, INC.



Mr. Mike Linder March 1, 2005 Page 3