

APPENDIX C

C.5 Checklist for Determining When Significant Licensing Action Has Taken Place That May Require An Additional Onsite Inspection

CHECKLIST FOR DETERMINING WHEN SIGNIFICANT LICENSING ACTION HAS TAKEN PLACE THAT MAY REQUIRE AN ADDITIONAL ONSITE INSPECTION

If recent licensing actions have resulted in one of the following, regional management should determine the need for performing an onsite inspection prior to the next routine inspection:

- 1. Does the licensing action result in increased authorization for types and quantities of radioactive material that could result in a significant potential for increased radiation exposure to the public and occupational workers?

No
 Yes (Describe)

Note: This can be identified by a change to a higher priority, i.e, from a Priority 2 to a Priority 1 license. Another "rule-of-thumb" for identifying a significant change in this area would be an increase in the authorized quantity from a millicurie amount to a curie amount.

- 2. Does the licensing action authorize a physical move of a facility or authorize use at a temporary job site(s)?

No
 Yes

- 3. Does the licensing action authorize satellite facilities where material will be used or stored?

No
 Yes

- 4. Does the licensing action increase the types of uses or disposal (incineration) of radioactive materials?

No
 Yes

- 5. Does the licensing action significantly increase the number of authorized users?

No
 Yes

6. RSO change?
 YES

136283

IDENTIFICATION OF SIGNIFICANT LICENSING ACTION POSSIBLE NEED FOR ONSITE INSPECTION PRIOR TO ROUTINE INSPECTION

Licensee: Rippincott

License No. 29-19573-01 Docket No. 03017800 Control No. 136283

An onsite inspection of the licensee identified above must be considered due to a recent significant licensing action involving one or more of the criteria described below. Additional information is attached (if needed).

Check all that apply:

- Increased types and uses
- Physical move or temporary job site
- Authorization of satellite facilities
- Increased disposal authorization
- Significant increase in number of authorized users
- Change in Radiation Safety Officer

Date of Last Inspection: 2/26/02 Results (Clear, #NOVs): NOV 35611

Date of Next Scheduled Inspection: 2/2007

Reviewer Recommendation and Justification:

Change 6/2006

No Change

License Reviewer: K. A. Modes

Date: 2/22/05

Change date of Next Inspection?

No

Yes New Inspection date: 6/06

Branch Chief: hus

Date: 2/24/05