NRC FÖRM 591M PART 1			U.S. NUCLEAR REGULATORY COMMISSION		
(10-2003) 10 CFR 2.201					
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
SteriGenics East Corporation			U.S. Nuclear Regulatory Commission		
75 Tilbury Road			Region I, 475 Allendale Road		
Salem, New Jersey 08079			King of Prussia, Pennsylvania 19406-1415		
REPORT 2005001					
		4. LICENSEE NUMBER(S)		5. DATE(S) OF IN	ISPECTION
030-22307		29-20900-01		February 9, 2005	
LICENSEE:					
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:					
1. Based on the inspection findings, no violations were identified.					
2. Previous violation(s) closed.					
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.					
Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s): IAW 10CFR 36.83, THE LICENSEE FAILED TO MAKE A					
24 HOUR REPORT WHEN THEIR STORAGE POOL CONDUCTIVITY EXCECOED 100 MIROSIEDEN /CM. THIS FAILURE WAS EXCECOED 100 MIROSIEDEN /CM. THE PROPER NOTIFICATION DETERMINED BY THE LICENSEE AND THE PROPER NOTIFICATION THE LICENSEE HAS ESTABLISHED					
EXCECOED 100 MEROSIEDEN /CM. THIS FAILURE WAS					
DETERMINED BY THE LICENSEE AND THE PROTECTIONSHED MADE AS REQUIRED. THE LICENSEE HAS ESTABLISHED MADE AS REQUIRED TO SUPPORT FUTURE TIMELY					
MADE AS REQUIRED. THE LICENSEE HAS ESTABLISHED MADE AS REQUIRED TO SUPPORT FUTURE TIMELY A FORMAL PROCEDURE TO SUPPORT FUTURE TIMELY REPORTING. (EUENT MOTIFICATION 40704)					
a sound procedure to support totale					
A FORMAN (CITENT NOTIFICATION 40 104)					
REPORTING. (COCI.					
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.					
(Violations and Corrective Actions)					
'					
Licensee's Statement of Corrective Actions for Item 4, above.					
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
Title	Print	ted Name	Sig	nature	Date
LICENSEE'S REPRESENTATIVE	Stephen	Ferraro	Stephen	Fenaro	2/9/05
NRC INSPECTOR	James Schmidt		Javes -	Schrift	2/9/05

NRC FORM 591M PART 1 (10-2003)

G:\Reference\Blank Forms\NRC591MPart1.wpd

NRC-002