

U.S. NUCLEAR REGULATORY COMMISSION		Conversation Date: March 17, 2005	
TELEPHONE CONVERSATION RECORD		Time:	
Mail Control No.:	License No.:	Docket No.:	
022429	New	030-36779	
Licensee/Applicant Participant(s):	Organization:	Telephone No.:	
Terry Naughton, Director of Sales	ASP, Inc.	1-800-236-6243	
Person(s) Calling: MSIB: Jonathan Rivera			
Subject: Clarifications to deficiency response dated March 7, 2005, related to new license application for exempt distribution of mb-microtec watches containing tritium.			
<p>Summary:</p> <p>The licensee provided the following clarifications, in response to email dated 3/16/05:</p> <ol style="list-style-type: none"> 1. The diagram submitted in response to no. 3(b) in deficiency email sent 2/18/05, is for Model P6500, which features a steel back with 4 screws. The diagram submitted in the third picture of the attachment to the application dated 12/10/04, is for Model P6502, which features a steel back which, as a whole piece, is screwed onto the watch. A special tool is needed to unscrew the steel back off the Model P6502. 2. The manufacturer, mb-microtec, does not follow a specific quality assurance standard for the manufacture of timepieces. For quality control purposes, mb-microtec performs vibration tests per ANSI/HPS N43.4-2000. REVIEWER NOTE: The manufacturer's quality control procedures for these timepieces are described on the 6th page of the text to the application dated 12/10/04. 3. Mr. Naughton confirmed his understanding that the recordkeeping and reporting requirements for his products are under 10 CFR 32.16, and not 10 CFR 32.25. 			
Action Required/Taken:		Clarification	
Prepared By: Jonathan Rivera		Date: March 17, 2005	