Justine Burza - EDO Bullet Status PB Unit 1 Head

From: Melvin Holmberg To: Louden, Patrick Date: 5/20/04 4:18PM Subject: EDO Bullet Status PB Unit 1 Head

Pat,

3

.- [^]

Attached is my summary EDO bullet on the status of the Point Beach Unit 1 head inspection.

CC: Caniano, Roy; Harold Chernoff; Hills, David; Morris, R. Michael; Pederson, Cynthia

RTT TI Page 1

C:\TEMP\GW}00001.TMP

ŝ

Page 1

Mail Envelope Properties (40AD20A2.726 : 16 : 24412)

Subject:EDO Bullet Status PB Unit 1 HeadCreation Date:5/20/04 4:18PMFrom:Melvin Holmberg

Created By:

MSH@nrc.gov

Recipients

nrc.gov ch_po.CH_DO CDP1 CC (Cynthia Pederson) DEH CC (David Hills) PLL (Patrick Louden) RJC1 CC (Roy Caniano) RMM3 CC (R. Michael Morris)

nrc.gov

owf4_po.OWFN_DO HKC CC (Harold Chernoff)

Post Office

ch_po.CH_DO owf4_po.OWFN_DO

nrc.gov nrc.gov

Files	Size	Date & Time
pbEDObullet.wpd	4365	05/20/04 04:14PM
MESSAGE	603	05/20/04 04:18PM
Options		
Expiration Date:	None	
Priority:	Standard	
Reply Requested:	No	

Concealed Subject: Security:

Return Notification:

No Standard

None

Ultrasonic and visual examination of the 49 Unit 1 upper vessel head penetration nozzles and head vent line penetration are completed. Due to limitations in ultrasonic examination coverage at the bottom end of 17 penetration nozzle locations, the licensee has requested relaxation (currently under staff review) from examination coverage requirements in Order EA-03-009. No leaking nozzles or evidence of vessel head wastage have been identified. However, linear indications in nozzle No. 26 J-groove weld were identified which required repair. A temper bead weld repair for this nozzle has been completed and the licensee's Code relief request to approve this repair methodology is currently under review by NRR staff.

•