

APPENDIX C

**C.5 Checklist for Determining When Significant Licensing Action Has Taken Place That May Require An Additional Onsite Inspection**

**CHECKLIST FOR DETERMINING WHEN SIGNIFICANT LICENSING ACTION HAS TAKEN PLACE THAT MAY REQUIRE AN ADDITIONAL ONSITE INSPECTION**

If recent licensing actions have resulted in one of the following, regional management should determine the need for performing an onsite inspection prior to the next routine inspection:

1. Does the licensing action result in increased authorization for types and quantities of radioactive material that could result in a significant potential for increased radiation exposure to the public and occupational workers?

- No
- Yes (Describe)

*Note:* This can be identified by a change to a higher priority, i.e. from a Priority 2 to a Priority 1 license. Another "rule-of-thumb" for identifying a significant change in this area would be an increase in the authorized quantity from a millicurie amount to a curie amount.

2. Does the licensing action authorize a physical move of a facility or authorize use at a temporary job site(s)?

- No
- Yes

3. Does the licensing action authorize satellite facilities where material will be used or stored?

- No
- Yes

4. Does the licensing action increase the types of uses or disposal (incineration) of radioactive materials?

- No
- Yes

5. Does the licensing action significantly increase the number of authorized users?

- No
- Yes