Harold Chernoff - Extent of visual examinations and transducer failure.

w/hold in part

From: To: Date: Subject: Melvin Holmberg KM Harold Chernoff KM Wed, May 12, 2004 10:05 AM Extent of visual examinations and transducer failure.

Harold,

CC:

To keep NRR tech staff up to date on other issues which have not been discussed.

1) For the rotating probe a 60 degree shear wave transducer failed its post examination cal check (channel 6 data). The licensee does not consider this to affect the qualification of the probe to detect PWSCC due to the multitude of other transducers on this probe.

Andrea Keim; Hills, David; Lakshminaras Raghavan; Timothy Steingass; William Koo

Information in this record was deleted in accordance with the Freedom of Information Act, exemptions 5 FOLA

T-8