



April 26, 2005

US Nuclear Regulatory Commission  
Region I  
Nuclear Materials Safety Branch  
475 Allendale Road  
King of Prussia, PA 19406-1415

***Please expedite this licensing request.***

**RE:** Material License #37-30872-01MD

03036484

Dear License Reviewer:

Please amend the above referenced material license to reflect the following modification at your very earliest convenience:

We would like to add an item under License Condition #11 as follows:

<u>Isotope</u>	<u>Source Model Number</u>	<u>Maximum Activity Per Source</u>
Cs-137	IPL GF-xxx (disk)	10 uCi

The well for our Multi-Channel Analyzer has a flat head crystal with one Pi geometry. Our current Cs-137 rod source (0.1 uCi) does not yield sufficient count rates within a reasonable and usable period of time. Thus, we are in need of a new and stronger source.

All other items relating to our radioactive material license and established Radiation Safety Program remain unchanged at this time.

Please contact me personally at (724)986-7437 with any questions and/or comments. Thank you for your prompt assistance regarding this matter.

Sincerely,

S. Duann Vanderslice, RPh, BCNP, FAPhA  
Managing Director/RSO

136911  
NMSS/RGNI MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

4/26/2005, and to inform you that the initial processing which includes an administrative review has been performed.



Amendment 37-30872-01M0  
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.



Please provide to this office within 30 days of your receipt of this card

---

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 136911.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.

: (FOR LFMS USE)  
: INFORMATION FROM LTS  
: -----  
:  
: Program Code: 02500  
: Status Code: 0  
: Fee Category: 7C  
: Exp. Date: 20140430  
: Fee Comments: \_\_\_\_\_  
: Decom Fin Assur Reqd: N  
: ::

BETWEEN:

License Fee Management Branch, ARM  
and  
Regional Licensing Sections

LICENSE FEE TRANSMITTAL

A. REGION I

1. APPLICATION ATTACHED  
Applicant/Licensee: HOPE PHARMACEUTICAL, LLC  
Received Date: 20050426  
Docket No: 3036484  
Control No.: 136911  
License No.: 37-30872-01MD  
Action Type: Amendment

2. FEE ATTACHED  
Amount:   /    
Check No.:           

3. COMMENTS

Signed Rebecca J. Jervis  
Date 4/26/2005

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered /\_/)

1. Fee Category and Amount: \_\_\_\_\_  
2. Correct Fee Paid. Application may be processed for:  
Amendment \_\_\_\_\_  
Renewal \_\_\_\_\_  
License \_\_\_\_\_  
3. OTHER \_\_\_\_\_

Signed \_\_\_\_\_  
Date \_\_\_\_\_