

<b>TELEPHONE CONVERSATION RECORD</b>	<b>Date:</b> April 21, 2005	<b>Time:</b> 08:30
<b>Mail Control No.:</b> N/A <b>Inspection No.:</b> N/A	<b>License No.:</b> 45-25268-01	<b>Docket No.:</b> 030-33271
<b>Person Called:</b> Michael Dickey, Radiation Safety Officer	<b>Licensee:</b> Green Bay Packaging, Inc.	<b>Telephone No.:</b> 540-678-2632
<b>Person Calling:</b> Steven Courtemanche/(610) 337-5075		
<b>Subject:</b> NMED Event No. 050045.		
<u>Summary:</u> I left a message on Mr. Dickey's voice-mail for her to get back in touch with me.  10:45 I asked Mr. Dickey what the model number and the serial number of the gauge which had a malfunctioning indicator light. Mr. Dickey stated that the gauge model number was OD-120 and its serial number was W192-067-2181. Mr. Dickey also confirmed that Honeywell-Measurex came on site to replace the indicator light.		
<b>Action Required/Taken:</b> Place into ADAMS.		
<b>Prepared by Steven Courtemanche</b>	<b>Date:</b> April 21, 2005	