

## Danville Diagnostic Imaging Center

125 Executive Drive Bline Danville, VA 434 0N 1. 434/793-1043 FAX 434/799-0066

05 APR -4 P12:31

US Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406-1415

March 30, 2005

Dear Sir:

030 31983

Danville Diagnostic Imaging Center requests a change in NRC license number 45-25118-01 so that we may administer 99m-Technetium Cardiolite in the office of Dr. Stephen Davis, MD, located at 200 Deer Run Road, Danville, VA 24540. In section 10.B.1 of our present license, administration of licensed material in the office of Dr. Stephen is already in place. This notification is being written because Dr. Davis is moving his office to the Deer Run location.

We will continue to comply with the provisions of 10 CFR 35.29, 10 CFR.80 and with provisions stated in previous correspondence.

Enclosed is a letter from Dr. Davis authorizing Danville Diagnostic Imaging Center to administer 99m-Technetium Cardiolite at his office. The office is located on a single story, private building. There are no other occupants in this single office building.

Thank you for this consideration.

Respectfully Submitted,

G. Michael Spencer, MD Radiation Safety Officer

> | 360|| nhass/rgni materials-002

Stephen Davis, MD 200 Deer Run Road Danville, VA 24540

March 30, 2005

US Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406-1415

Dear Sir:

I grant approval to Danville Diagnostic Imaging Center for the use of radioactive 99m-Technetium Cardiolite at my office located at 200 Deer Run Road, Danville, VA 24540. Our office does not have an active NRC license. This notification is due to the fact that I am moving my office to a new location. My adult cardiology practice will be the only occupant in this single story building.

I understand that I am under no obligation to have these studies performed in my office but my approval will allow the administration of 99m-Technetium in conjunction with stress testing and subsequent myocardial scanning at Danville Diagnostic Imaging Center, should I desire such examinations, and should the US NRC grant Danville Diagnostic Imaging Center approval to perform such examinations.

Sincerely,

Stephen Davis MD

This is to acknowledge	the receipt of your letter/application dated
3 30 2005 includes an administrat	, and to inform you that the initial processing which tive review has been performed.
technical reviewer.	eut H5-25118-01 inistrative omissions. Your application was assigned to a Please note that the technical review may identify additional e additional information.
Please provide to th	is office within 30 days of your receipt of this card
, , ,	has been forwarded to our License Fee & Accounts Receivable ct you separately if there is a fee issue involved.
When calling to inquire	assigned Mail Control Number 136811 about this action, please refer to this control number. (0) 337-5398, or 337-5260.
NRC FORM 532 (RI) (6-96)	Sincerely, Licensing Assistance Team Leader

.

	: (FOR LFMS USE) : INFORMATION FROM LTS
BETWEEN:	:
License Fee Management Branch, ARM and Regional Licensing Sections	: : Program Code: 02200 : Status Code: 0 : Fee Category: 7C : Exp. Date: 20051130 : Fee Comments:
LICENSE FEE TRANSMITTAL	
A. REGION I	
1. APPLICATION ATTACHED Applicant/Licensee: DANVILLE DI Received Date: 20050404 Docket No: 3031883 Control No.: 136811 License No.: 45-25118-01 Action Type: Amendment	
2. FEE ATTACHED Amount: Check No.:	
3. COMMENTS Signe Date	d Phere Junet
B. LICENSE FEE MANAGEMENT BRANCH (Ch	neck when milestone 03 is entered //)
1. Fee Category and Amount:	<del></del>
2. Correct Fee Paid. Application m Amendment Renewal License	may be processed for:
3. OTHER	<del></del>
Signe	ed

Date