NRC FORM 591M PAR' (10-2003) 10 CFR 2.201		ECTION REPORT A		U.S. NUCLEAR REGULATO EINSPECTION	ORY COMMISSION
1. LICENSEE/LOCATION INSPECTED: Engineering Consulting Services, Ltd. 166 Wndy Hill Lane Winchester, VA 22602			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
REPORT NUMBER(S) 3. DOCKET NUMBER(S)	2005-001	4. LICENSEE NUMBER(S)		E DATE(S) OF IN	ISPECTION
030-36489		45-30874-01		5. DATE(S) OF INSPECTION April (4), 2005	
LICENSEE:		45-50074-01		April 6 , 2005	
Nuclear Regulatory Com of procedures and repres 1. Based on the 2. Previous viol 3. The violation non-repetitive, a exercise discret 4. During this ir cited. This form	mission (NRC) rules and sentative records, interview inspection findings, no viation(s) closed. (s), specifically described and corrective action was ion, were satisfied. Non-Cited Violation(s) via a NOTICE OF VIOLATION and Corrective Actions)	d regulations and the condiews with personnel, and of violations were identified. If to you by the inspector as or is being taken, and the rewas/were discussed involving activities, as described belontion, which may be subjected.	tions of your license. The oservations by the inspector of the inspector o		ctive examinations are as follows: ere self-identified, G-1600, to
	Licensee's	s Statement of Correct	tive Actions for Item 4	1, above.	
corrective actions is made date when full compliance Title	30 days, the actions des e in accordance with the e will be achieved). I unde	cribed by me to the inspectorequirements of 10 CFR 2.2	or will be taken to correct the 01 (corrective steps already n response to NRC will be r	e violations identified. This st y taken, corrective steps whic required, unless specifically re gnature	h will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Jenny M. Johans	sen	Semme	chance	4/8/05

NRC FORM 591M PART 1 (10-2003)