NRC FORM 591M PAF (10-2003)	RT 1		U.S. NUCLEAR RE	GULATORY COMMISSION
10 CFR 2.201	CAEETV INCDE	CTION DEDODT AN	D COMPLIANCE INSPECT	ON
,	SAFETT INSPE	STION REPORT AN	D COMPLIANCE INSPECTI	ON
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE	
Progressive Engineering Group, Inc. 1208 Idaho Street Lewiston, Idaho 83501			USNRC Region IV	
			USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005	
			Annigion, rexas 76011-4005	
REPORT NUMBER(S)	2005-001	4. LIOENOEE NUMBER(O)	Is DATE(O) OF NO	PECTION
3. DOCKET NUMBER(S) 030-35017		4. LICENSEE NUMBER(S) 11-27629-01	5. DATE(S) OF INS <b>05/18/2005</b>	
LICENSEE:		11-27023-01	00/10/2000	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X				
cited. This form			d/or attached, were in violation of NRC requiposting in accordance with 10 CFR 19.11.	rements and are being
corrective actions is mad	n 30 days, the actions desc le in accordance with the re se will be achieved). I under	ribed by me to the inspector will equirements of 10 CFR 2.201 (c	e Actions for Item 4, above.  be taken to correct the violations identified. orrective steps already taken, corrective step ponse to NRC will be required, unless specific Signature	s which will be taken,
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	Rick	Muñoz	/RA/	05/18/2005