

<b>TELEPHONE CONVERSATION RECORD</b>	<b>Date:</b> May 25, 2005	<b>Time:</b> 10:25
<b>Mail Control No.:</b> 136562 <b>Inspection No.:</b> N/A	<b>License No.:</b> 06-31024-01	<b>Docket No.:</b> 030-36882
<b>Person Called:</b> Chris Beaulieu, Facility Manager	<b>Licensee:</b> Diagnostic Imaging of Southbury	<b>Telephone No.:</b> 203-267-5800
<b>Person Calling:</b> Steven Courtemanche/(610) 337-5075		
<b>Subject:</b> Non-response to a Request for Additional Information.		
<p><u>Summary:</u> I left messages on the voice-mails for Mr. Beaulieu and Stu Korchin, Consulting Medical Physicist for them to get back in touch with me concerning the fact that a response has not been received answering the questions in our April 8, 2005 letter.</p> <p>11:00 Stu Korchin returned my call. He stated that he had e-mailed a response for the licensee last week. The licensee informed him that they would type it up and fax it to the NRC. Mr. Korchin said that he would contact the licensee and determine what was the status of the response. I thanked him for his attention to the matter.</p> <p>12:45 I spoke with Chris Beaulieu. He stated that he had only gotten the signature of Dr. Lehman yesterday and would fax the letter to the NRC. He asked me where he could get a Form 313 since the RAI requested that one be filled out for new applications. I informed him that he could photocopy one from one of the NUREG-1556 books. If he had any problems finding one, he could contact me and I would fax one to him.</p>		
<b>Action Required/Taken:</b> Place into ADAMS.		
<b>Prepared by</b> Steven Courtemanche	<b>Date:</b> May 25, 2005	