

RP
EXS

NMC > Sites > Point Beach - Action Request > Corrective Actn Program (CAP) AR

Section 1

Activity Request Id: CAP055986
Activity Type: CAP Submit Date: 4/23/2004 11:18:23 AM

One Line Description: Evaluate use of RP Greeter at Containment hatches during outage periods

Detailed Description: 4/23/2004 11:18:23 AM - THOMAS, STU:
During a region III NRC RP inspection, the inspector commented that he is used to seeing other plants using an RPT as a greeter at the containment hatches. The greeter typically challenges radworkers prior to entering containment to ensure proper dressout, proper dosimetry, proper RWP, and direction with whom to check in with from RP inside containment. It was further commented at the exit by the site's senior resident inspector, that if we'd have had this in place through out this outage, we could have potentially prevented the rad event of having an individual receive a dose alarm while working in containment on a PAB RWP.

Initiator: THOMAS, STU Initiator Department: PR Radiation Protection PB

Date/Time of Discovery: 4/23/2004 11:09:42 AM Date/Time of Occurrence: 4/23/2004 11:09:42 AM

Identified By: NRC System: (None)

Equipment # (1st): (None) Equipment Type (1st): (None)

Equipment # (2nd): (None) Equipment Type (2nd): (None)

Equipment # (3rd): (None) Equipment Type (3rd): (None)

Site/Unit: Point Beach - Common

Why did this occur?: 4/23/2004 11:18:23 AM - THOMAS, STU:
Potentially caused by ineffective benchmarking. INPO also noted that RP was not effectively benchmarking the best performers in the industry.

Immediate Action Taken: 4/23/2004 11:18:23 AM - THOMAS, STU:
Wrote AR.

Recommendations: 4/23/2004 11:18:23 AM - THOMAS, STU:
Perform a condition evaluation.

Develop guidance and station individual at the 66' hatch entrance.

Share this AR with NMC fleet RPM's during weekly RPM phone call.

Notify Me During Eval?: N SRO Review Required?: N

Section 2

Operability Status: NA Compensatory Actions: N

Basis for Operability: 4/23/2004 2:16:02 PM - RAASCH, DEAN:
This is a suggestion for site improvement. This issue does not affect the operability of Systems, Structures, or Components related to safety.

Unplanned TSAC Entry: N External Notification: N