From:

Melvin Holmberg

To:

Hills, David <

Date:

5/11/04 11:30AM

Subject:

Fwd: Repair on Nozzle 26

David,

The attached file has the Framatome ID temper bead repair steps to be performed at PB U1 nozzle 26. I believe this drawing is proprietary. Pat Louden requested this drawing to help explain repairs and issues.

CC:

Louden, Patrick

Information in this record was deleted in accordance with the Freedom of Information Act, exemptions 44

L-25

Mail Envelope Properties (40A0FF88.50A:16:24412)

Subject:

Fwd: Repair on Nozzle 26

Creation Date:

5/11/04 11:30AM

From:

Melvin Holmberg

Created By:

MSH@nrc.gov

Recipients

nrc.gov

ch_po.CH_DO

DEH (David Hills)

PLL CC (Patrick Louden)

Post Office

ch_po.CH_DO

Route

nrc.gov

Files

Size

Date & Time

Mail

MESSAGE

725

05/11/04 11:30AM

Options

Expiration Date:

None

Priority:

Standard

Reply Requested:

No

Return Notification:

None

Concealed Subject:

No

Security:

Standard

From:

To:

"RMM3@NRC.GOV" <rmm3@nrc.gov>
"PLL@NRC.GOV" <pli@nrc.gov>, "RMM3@NRC.GOV" <rmm3@nrc.gov>
5/11/04 11:23AM

Date:

Subject:

Repair on Nozzle 26

CC:

"MSH@NRC.GOV" <msh@nrc.gov>, "HKC@NRC.GOV" <hkc@nrc.gov>

Mail Envelope Properties (40A0FDEC,571:8:58737)

Subject:

Repair on Nozzle 26

Creation Date:

2/7/06 5:28AM

From:

"RMM3@NRC.GOV" <rmm3@nrc.gov>

Created By:

RMM3@nrc.gov

Recipients

nrc.gov

ch_po.CH_DO

PLL (Patrick Louden)

RMM3 (R. Michael Morris)

MSH CC (Melvin Holmberg)

nrc.gov

owf4_po.OWFN_DO

HKC CC (Harold Chernoff)

Post Office

ch po.CH_DO

owf4_po.OWFN_DO

Route

nrc.gov

nrc.gov

Files

Size

Date & Time

02/07/06 05:28AM

MESSAGE

2

Document.pdf

250561

Mime.822

344300

Options

Expiration Date:

Priority:

None Standard

Reply Requested:

No

Return Notification:

None

Concealed Subject:

No

Security:

Standard