

SAFEGUARDS INFORMATION

Tennessee Valley Authority, Post Office Box 2000, Spring City, Tennessee 37381-2000

William R. Lagergren, Jr.
Site Vice President, Watts Bar Nuclear Plant

MAY 31 2005

ICM B.5.b

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
11555 Rockville Pike
Rockville, Maryland 20852

Gentlemen:

In the Matter of) Docket No.50-390
Tennessee Valley Authority)

**WATTS BAR NUCLEAR PLANT (WBN) UNIT 1 - RESPONSE TO NRC
GUIDANCE REGARDING MITIGATION STRATEGIES**

The NRC issued Orders for Interim Safeguards and Security Compensatory Measures ("Order EA-02-026" or "ICM Order") dated February 25, 2002, for WBN.

Order EA-02-026 imposed requirements on nuclear power plants licensed pursuant to the Atomic Energy Act of 1954 and Title 10 of the Code of Federal Regulations. Section III.A of the Order required licensees to implement certain changes in physical security plans and safeguards contingency plans on an interim basis until final requirements were established. Among other requirements, TVA was required to complete implementation of the requirements of Section II.B.5.b. of Order EA-02-026 by August 31, 2002.

Subsequently, the NRC issued Orders, dated April 29, 2003, *Requiring Compliance with Revised Design Basis Threat for Operating Power Reactors* ("Order EA-03-086" or "DBT Order") and other security related Orders (collectively "Orders") for WBN. In many ways, Order EA-03-086 complemented or superseded requirements the interim measures imposed by Order EA-02-026.

NOTE: ENCLOSURE 1 TO THIS LETTER CONTAINS "SAFEGUARDS INFORMATION" AND MUST BE PROTECTED ACCORDINGLY. UPON REMOVAL OF THE ENCLOSURE, THIS LETTER IS "DECONTROLLED."

SAFEGUARDS INFORMATION

* IFSB
11

SAFEGUARDS INFORMATION

U.S. Nuclear Regulatory Commission

Page 2

MAY 31 2005

As required by Order EA-03-086, the plans for the above-mentioned licensed facility have been implemented. Subsequently, TVA was requested to respond to the letter from J. E. Dyer, Director, Office of Nuclear Reactor Regulation, dated February 25, 2005, *NRC Staff Guidance for Use in Achieving Satisfactory Compliance with February 25, 2002, Order Section B.5.b*, ("NRC B.5.b. Guidance") by May 31, 2005, and to implement appropriate enhancement to current mitigation strategies by August 31, 2005. Specifically, nuclear power plant licensees were requested by Enclosure 2, *Developing Mitigating Strategies/Guidance for Nuclear Power Plants to Respond to Loss of Large Areas of the Plant in Accordance with B.5.b of the February 25, 2002, Order* (dated February 24, 2005) ("NRC B.5.b. Guidance"), to the February 25, 2005, letter to review the Areas of Consideration delineated in Attachment A to that Enclosure and evaluate additional considerations for potential inclusion in the licensees' mitigating strategies that licensees deemed appropriate in accordance to Attachment B to that Enclosure.

Subsequently, the Nuclear Energy Institute ("NEI"), in conjunction with the NEI Security Working Group, developed and issued guidance for licensee use ("NEI Guidance") to assist licensees in responding to the February 25, 2005, letter.

As requested in the February 25, 2005, letter, TVA has reviewed the information in Attachments A and B in accordance with the NEI Guidance and is hereby submitting, as a Safeguards Information Enclosure to this letter (Enclosure 1), TVA's evaluation of the information the NRC provided. Enclosure 1 reflects the results of a comprehensive and thorough review of the guidance and describes the considerations that TVA either has already or intends to implement at WBN by August 31, 2005.

The primary guiding principles used in the conduct of this evaluation were (1) whether or not equipment and resources were "readily available," and (2) if equipment is readily available, can it be effectively utilized in a licensee's mitigating strategy. TVA considered "readily available" to mean that the equipment or resources was already licensee owned, under contract, or part of an existing Memorandum of

NOTE: ENCLOSURE 1 TO THIS LETTER CONTAINS "SAFEGUARDS INFORMATION" AND MUST BE PROTECTED ACCORDINGLY. UPON REMOVAL OF THE ENCLOSURE, THIS LETTER IS "DECONTROLLED."

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

U.S. Nuclear Regulatory Commission

Page 3

MAY 31 2005

Understanding. Further, even if equipment and resources are readily available, the second criterion is to ensure that the equipment can be used in a mitigating strategy in an effective manner. Even if the equipment is readily available, it is of no value if it cannot be effective in implementing the mitigating strategy.

In accordance with these principles, mitigative strategies are being implemented to address the NRC B.5.b. Guidance. These actions are considered to be commitments for that purpose and will be managed in accordance with TVA's commitment management system.

Enclosure 2 to this letter contains the commitment to complete the actions regarding the implementation of the mitigative strategies to address NRC's B.5.b Guidance.

If you have any questions about this response, please contact P. L. Pace at (423) 365-1824.

Sincerely,



W. R. Lagergren

Enclosures

Cc (See page 4)

NOTE: ENCLOSURE 1 TO THIS LETTER CONTAINS "SAFEGUARDS INFORMATION" AND MUST BE PROTECTED ACCORDINGLY. UPON REMOVAL OF THE ENCLOSURE, THIS LETTER IS "DECONTROLLED."

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

U.S. Nuclear Regulatory Commission

Page 4

MAY 31 2005

Enclosures

cc Enclosures:

NRC Resident Inspector
Watts Bar Nuclear Plant
1260 Nuclear Plant Road
Spring City, Tennessee 37381

Mr. D. V. Pickett, Project Manager
U.S. Nuclear Regulatory Commission
MS O8G9a
One White Flint North
11555 Rockville Pike
Rockville, Maryland 20852-2738

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
Sam Nunn Atlanta Federal Center
61 Forsyth St., SW, Suite 23T85
Atlanta, Georgia 30303

J. E. Dyer, Director,
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
MS O8G9a
One White Flint North
11555 Rockville Pike
Rockville, Maryland 20852-2738

NOTE: ENCLOSURE 1 TO THIS LETTER CONTAINS "SAFEGUARDS INFORMATION" AND
MUST BE PROTECTED ACCORDINGLY. UPON REMOVAL OF THE ENCLOSURE, THIS LETTER
IS "DECONTROLLED."

SAFEGUARDS INFORMATION