NRC FORM 591M PAI (10-2003)	RT 1			U.S. NUCLEAR REGULA	TORY COMMISSION
10 CFR 2.201	SAFETY INSPE	ECTION REPORT A			
LICENSEE/LOCATION INSPECTED: Washington Testing & Consulting Services P.O. Box 327 Falls Church, VA 22040-0327			NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
REPORT NUMBER(S)	2005-001	A MOENOEE NUMBER(O)		5 DATE(O) OF	NODECTION
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S) 45-25459-01		5. DATE(S) OF	INSPECTION
030-34905 4 LICENSEE:		40-20409-01		May 19, 2005	
Nuclear Regulatory Cor of procedures and repre- 1. Based on the second	mmission (NRC) rules and esentative records, interviole inspection findings, no collation(s) closed. on(s), specifically described and corrective action was betion, were satisfied.	d regulations and the condit ews with personnel, and ob- violations were identified. If to you by the inspector as a or is being taken, and the re-	ions of your license. The servations by the inspec non-cited violations, are n emaining criteria in the NF	adiation safety and to comple inspection consisted of setor. The inspection findings not being cited because they RC Enforcement Policy, NUF	elective examinations are as follows: were self-identified, REG-1600, to
cited. This form	n is a NOTICE OF VIOLA's and Corrective Actions)	TION, which may be subject	to posting in accordance	n violation of NRC requirement with 10 CFR 19.11.	
corrective actions is mad	n 30 days, the actions des de in accordance with the ce will be achieved). I unde Prin	requirements of 10 CFR 2.20	r will be taken to correct t 01 (corrective steps alrea n response to NRC will be	the violations identified. This dy taken, corrective steps we required, unless specifically Signature	nich will be taken,
NRC INSPECTOR	Jenny M. Johans	sen	1 1/6 1	6/	1/191-
NRC FORM 591M PART 1		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1 Prefry	Man	1/1/01