

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Caribbean Inspection & NDT Services P. O. Box 696 Santa Isabel, Puerto Rico 00757		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 2005-001			
3. DOCKET NUMBER(S) 030-36301	4. LICENSE NUMBER(S) 52-25629-01	5. DATE(S) OF INSPECTION May 23 2005	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 20.1101 (c) requires an annual program review. Contrary to the above, the licensee did not perform an annual review for 2004. The licensee will use the model audit form in Appendix I of NUREG-1556, Vol. 2.

10 CFR 34.27 (e) requires the licensee to leak test the depleted uranium. ~~Contrary~~ every 12 months. Contrary to the above, between 10-2-2003 and 5-23-2005 the licensee did not leak test the depleted uranium. The licensee will contact the manufacturer for a leak test kit + will leak test the depleted uranium.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Thomas Hankins	<i>TH</i>	5-23-05
NRC INSPECTOR	K. Modes / J. Schmidt	<i>K. Modes / J. Schmidt</i>	5.23.05