| NRC FORM 591M PAR (10-2003) | T 1 | | ı | U.S. NUCLEAR REGULATO | RY COMMISSION |
|---|---|----------------------------|--|---|----------------|
| 10 CFR 2.201 | SAFETY INSI | PECTION REPORT | AND COMPLIANCE II | NSPECTION | |
| LICENSEE/LOCATION INSPECTED: E. L. Robinson Engineering Co. | | | 2. NRC/REGIONAL OFFICE | | |
| 5088 Washington Street West | | | U.S. Nuclear Regulatory Commission | | |
| Charleston, West Virginia 25313-1536 | | | Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415 | | |
| REPORT Nos 2005, 3. DOCKET NUMBER(S | | 4. LICENSE NUMBER(S | 5) | 5. DATE(S) OF INSPECTI | ON |
| | 035294 | | 5503-01 | May 19-20, 2005 | |
| LICENSEE: | | | | | |
| The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: | | | | | |
| Based on the inspection findings, no violations were identified. | | | | | |
| 2. Previous violation(s) closed. | | | | | |
| 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied. | | | | | |
| Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s): | | | | | |
| | | | | | |
| | | | | | |
| | | | ow and/or attached, were in vi subject to posting in accorda | iolation of NRC requirements ance with 10 CFR 19.11. | and are |
| 10 CFR 20.1101(c) requires that each licensee shall periodically (at least annually) review the radiation protection program content and implementation. | | | | | |
| Contrary to the above, as of May 20, 2005, the licensee did not perform a review of the radiation protection program for calendar year 2001 through 2004. | | | | | |
| The licensee's representative (RSO) indicated that audits of the program will be performed to meet the annual requirement. | | | | | |
| | | | | | |
| | | | ctive Actions for Item 4 | | |
| corrective actions is made | le in accordance with the ree will be achieved). I unde | requirements of 10 CFR 2.2 | 201 (corrective steps already t n response to NRC will be re | violations identified. This stat taken, corrective steps which equired, unless specifically req ignature | will be taken, |
| LICENSEE'S REPRESENTATIVE | | | | | |
| NRC INSPECTOR | Craig Gor | don | | /RA/ | 06/08/05 |