

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

June 15, 2005

Mr. Mark Hylen, President Kakivik Asset Management, LLC 5401 Fairbanks Street, Suite 3 Anchorage, Alaska 99518

SUBJECT: NRC INSPECTION REPORT 030-35371/05-001 (FORM 591M)

Dear Mr. Hylen:

This letter and the enclosed NRC Form 591M refers to the inspection conducted on June 8, 2005, at your facility in Kuparuk, Alaska. This inspection was an examination of activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selected examination of procedures and representative records, observation of licensed activities, and interviews with personnel. The inspection findings were discussed with Mr. Joey Labbs of your staff at the conclusion of the inspection. A final telephonic exit was conducted with you on June 14, 2005.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html.

Should you have any questions concerning this inspection, please contact Mr. James Thompson at (817) 276-6538 or the undersigned at (817) 860-8287.

Sincerely,

/RA/

Mark R. Shaffer, Chief Nuclear Materials Inspection Branch

Docket No.: 030-35371 License No.: 50-27667-01

Enclosure: As stated

cc w/enclosure:

Alaska Radiation Control Program Director

bcc w/enclosure (via ADAMS distrib): LDWert CLCain MRShaffer

JEWhitten JLThompson

KEGardin

NMIB

RIV Materials Docket File (5th floor)

SISP Review Completed: <u>JLT</u>

ADAMS: X Yes No Initials: JLT

X Publicly Available □ Non-Publicly Available □ Sensitive X Non-Sensitive

DOCUMENT NAME: s:\dnms\!nmib\!thompson\53537101.wpd

RIV:DNMS:NMIB	C:NMIB
JLThompson	MRShaffer
/RA/	/RA/
06/14/05	06/15/05

NRC FORM 591M PAF (10-2003) 10 CFR 2.201	RT 1 SAFETY INSPECTION REPORT AN	U.S. NUCLEAR REGULATO	RY COMMISSION	
1. LICENSEE/LOCATION INSPECTED: Kakivik Asset Management Kuparuk River Unit Kuparuk, Alaska		2. NRC/REGIONAL OFFICE USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
REPORT NUMBER(S)	05-001			
3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)	5. DATE(S) OF INSPECTION		
030-35371	50-27667-01	June 8, 2005		
the Nuclear Regulator examinations of proce findings are as follows X 1. Based on to X 2. Previous vi 3. The violation	the inspection findings, no violations were identified. olation(s) closed. on(s), specifically described to you by the inspector a on-repetitive, and corrective action was or is being tal	onditions of your license. The inspection consistersonnel, and observations by the inspector. The sersonnel, and observations by the inspector. The sersonnel, and observations by the inspector. The sersonnel, and the violations, are not being cited because ten, and the remaining criteria in the NRC Enforcen	ed of selective inspection they were selfnent Policy,	
are being cite	inspection certain of your activities, as described bd. This form is a NOTICE OF VIOLATION, which may s and Corrective Actions)	elow and/or attached, were in violation of NRC req be subject to posting in accordance with 10 CFR 1	uirements and 19.11.	
statement of corrective which will be taken, da specifically requested.		ctor will be taken to correct the violations identified s of 10 CFR 2.201 (corrective steps already taken, and that no further written response to NRC will be r	corrective steps equired, unless	
Title LICENSEE'S	Printed Name	Signature	Date	
REPRESENTATIVE				
NRC INSPECTOR	James L. Thompson	/RA/	06/14/05	