

U.S. NUCLEAR REGULATORY COMMISSION		Date: June 23, 2005		
TELEPHONE CONVERSATION RECORD		Time: 1535		
Mail Control 136357 or Report No(s).	License No(s). 52-21175-01	Docket No(s). 03019882		
<table style="width: 100%; border: none;"> <tr> <td style="width: 30%; vertical-align: top;"> Name of Licensee: Name of Participant(s): Telephone No. Subject: <small>(NOTE: This will be used as the Documents Title in ADAMS)</small> Summary: </td> <td style="vertical-align: top;"> Baxter Healthcare Corporation Angel Alicea (RSO) and Evet Vera 787-735-8021 Followup to Baxter Response Received June 20, 2005 Two items were discussed with Baxter personnel regarding the Baxter response provided to NRC letter dated May 17, 2005. 1) It was confirmed that the RSO will be a qualified, trained operator. 2) A typographical errors exist in the Deionizer Monitor Alarm Procedure, Procedure GAMMA-1. This procedure erroneously refers to the "Deionizer Monitor" as the "Outlet Monitor". The RSO stated that the procedure error will be corrected. Since this type procedure change is allowed without NRC concurrence (10 CFR 36.53(c)), no additional information is needed by the NRC at this time to support completion of the license renewal. </td> </tr> </table>			Name of Licensee: Name of Participant(s): Telephone No. Subject: <small>(NOTE: This will be used as the Documents Title in ADAMS)</small> Summary:	Baxter Healthcare Corporation Angel Alicea (RSO) and Evet Vera 787-735-8021 Followup to Baxter Response Received June 20, 2005 Two items were discussed with Baxter personnel regarding the Baxter response provided to NRC letter dated May 17, 2005. 1) It was confirmed that the RSO will be a qualified, trained operator. 2) A typographical errors exist in the Deionizer Monitor Alarm Procedure, Procedure GAMMA-1. This procedure erroneously refers to the "Deionizer Monitor" as the "Outlet Monitor". The RSO stated that the procedure error will be corrected. Since this type procedure change is allowed without NRC concurrence (10 CFR 36.53(c)), no additional information is needed by the NRC at this time to support completion of the license renewal.
Name of Licensee: Name of Participant(s): Telephone No. Subject: <small>(NOTE: This will be used as the Documents Title in ADAMS)</small> Summary:	Baxter Healthcare Corporation Angel Alicea (RSO) and Evet Vera 787-735-8021 Followup to Baxter Response Received June 20, 2005 Two items were discussed with Baxter personnel regarding the Baxter response provided to NRC letter dated May 17, 2005. 1) It was confirmed that the RSO will be a qualified, trained operator. 2) A typographical errors exist in the Deionizer Monitor Alarm Procedure, Procedure GAMMA-1. This procedure erroneously refers to the "Deionizer Monitor" as the "Outlet Monitor". The RSO stated that the procedure error will be corrected. Since this type procedure change is allowed without NRC concurrence (10 CFR 36.53(c)), no additional information is needed by the NRC at this time to support completion of the license renewal.			
Action Required:				
Prepared By: James Schmidt		Date: June 27, 2005		