| NRC FORM 591M PAR (10-2003) 10 CFR 2.201 | | N DEDODT AN | U.S. NUCLEAR RE | GULATORY COMMISSION | |
|--|--|--|---|---|--|
| 1. LICENSEE/LOCATION INSPECTED: Mallinkrodt, Inc. 26 Chapin Road Pine Brook, NJ 07058 REPORT Nos 2005-001 | | | 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415 | | |
| 3. DOCKET NUMBER(\$ 030-32951 | 3) 4. LICEN | SE NUMBER(S) -206-14MD | 5. DATE(S) OF II May 11, 20 | | |
| LICENSEE: | 2101 | 200 111112 | May 11, 20 | | |
| The inspection was an ex Nuclear Regulatory Comr of procedures and repres X 1. Based on the 2. Previous viol 3. The violation identified, non-r NUREG-1600, | nission (NRC) rules and regulations entative records, interviews with perse inspection findings, no violations value (s), specifically described to you by epetitive, and corrective action was a to exercise discretion, were satisfied | and the conditions sonnel, and observations were identified. the inspector as no or is being taken, and the conditions are something to the conditions are so | e as they relate to radiation safety and to comp of your license. The inspection consisted of s ations by the inspector. The inspection finding on-cited violations, are not being cited because and the remaining criteria in the NRC Enforcem | selective examinations gs are as follows: they were self- | |
| | | | and/or attached, were in violation of NRC requ bject to posting in accordance with 10 CFR 19 | | |
| corrective actions is made date when full compliance Title | 30 days, the actions described by me in accordance with the requirement | e to the inspector vits of 10 CFR 2.201 | ive Actions for Item 4, above. vill be taken to correct the violations identified. (corrective steps already taken, corrective steesponse to NRC will be required, unless specific signature. | eps which will be taken, | |
| LICENSEE'S REPRESENTATIVE NRC INSPECTOR | Joseph Nick | | /RA/ | 5/11/05 | |